ROUTE EVALUATION STUDY

FOR

High Bridge Wind Project

Town of Guilford, Chenango County, New York

Developer:

High Bridge Wind, LLC

Published: July 2019

Prepared By:

FISHER ASSOCIATES

FA Project No. 185048

TABLE OF CONTENTS

Page No.

I. Turbine Delivery Route to the Route Evaluation Study Area 2
II. Wind Turbine Generator (WTG) Deliveries in the Route Evaluation Study Area 3
III. Existing Road Conditions 3
A. Bridges and Load Posting Restrictions 3
B. Road Surfaces 4
C. Culvert Cover and Conditions 4
D. Overhead Clearance 5
E. Route Segment Assessment 5
IV. Intersection Modifications 9
V. Project Trip Generation Characteristics 9
A. Number, Frequency, and Timing of Vehicle Trips 9
B. Approach and Departure Routes for Trucks Carrying Water, Fuels or Chemicals 14
C. Conceptual Transportation and Approach / Departure Routes for Workers and Employees 14
VI. Traffic and Transportation Impacts 15
A. Overview 15
B. Over-sized Deliveries 15
C. Measures to Mitigate for Impacts to Traffic and Transportation 16
D. Road Use and Restoration Agreements 18
VII. Project Impact on Mass Transit 19
VIII. Traffic and Accident Data 19
IX. School District Bus Routes and Emergency Service Providers 22

Appendix A

Figure 1a: Project Location and Route Evaluation Study Area
Figure 1b: Project Layout
Figure 2: Transport Routes in the Route Evaluation Study Area
Figure 3: Road Width and Type
Figure 4: Culvert Type and Diameter
Figure 5: Culvert Cover and Condition
Figure 6: Overhead Crossings
Figure 7: Load Posting
Figure 8: Intersection improvements
Figure 9: Emergency Services

Appendix B – *Traffic and Accident Information and Analysis*

References

1) Project Layout prepared by High Bridge Wind, LLC and Fisher Associates.

Project Overview
Fisher Associates, P.E., L.S., L.A., D.P.C. (Fisher) has been contracted by High Bridge Wind, LLC (High Bridge Wind or Applicant) to complete a Route Evaluation Study (Study) for the proposed High Bridge Wind Project (Project).

The Study Area is located in the Town of Guilford, Chenango County, New York, as depicted in Appendix A, Figure 1a. The Project is a proposed wind-powered electric generating project that includes the installation and operation of up to 25 wind turbines and associated underground electrical collection lines, access roads, meteorological towers, an operation and maintenance (O&M) facility, and electrical substation yards with a battery storage component. The collective area within which all Project components will be located is defined as the Project Area as depicted in Figure 1b. The Route Evaluation Study Area (Study Area) encompasses all transportation routes from where they exit Interstate 88 to where they end at the delivery site.

The purpose of this Study is to:

- Identify a feasible route for delivering wind turbine components to and throughout the Facility Site;
- Document the condition of local roads, including pavement conditions and the location of culverts or bridges that could be affected by oversize and overweight deliveries;
- Document the overhead utility (cable, electric and phone) clearances over public roads and identify any which do not provide adequate clearance;
- Document the tree overhang over public roads and evaluate for adequate clearance; and
- Identify intersections in the Study Area that may require modification to allow delivery of wind turbine components.

High Bridge Wind's consultant drove all potential arrival and departure routes within the Study Area that could provide access routes to turbines and identified road conditions and potential obstacles to delivery of turbine components during construction (e.g., road width, turning radii, overhead clearance, presence of bridges and culverts, presence of steep slopes, etc.). Sections II through V of this Route Evaluation Study detail the field evaluation of the potential delivery and construction vehicle transportation routes within the Study Area that was conducted between 4/1/19 and 4/2/19. The condition of the roads was noted by visual inspection. Additionally, roadside features, bridge and roadway horizontal/vertical restrictions, bridge/culvert locations, and possible restricted intersection radii locations were also included in the evaluation. A formal study will be conducted prior to construction to determine if roads can handle construction traffic consistent with Road Use Agreements (RUAs) with the affected local governments (i.e., the Town of Guilford and Chenango County).

I. Turbine Delivery Route to the Route Evaluation Study Area

Wind turbine components are delivered using specialized oversized/overweight (OS/OW) haulers that require special consideration during project planning. Final routes to the Study Area will depend on the turbine suppliers and the source of the shipments. For this survey, Fisher assumed components would be transported to the Study Area via Interstate 88.

Delivery vehicles would approach the Study Area from the South on Interstate 88 to SR 8 as depicted in Appendix A, Figure 2.

The intersections with SR 8 at the Interstate 88 off ramps appear to be open enough to permit the movement of the component delivery vehicles. From SR 8, delivery vehicles could enter the Study Area using County Highway 35, County Highway 37, or Shumway Hill Road. These intersections appear to require some improvement to permit the movement of the component delivery vehicles. The hauler also will need to review these intersection for overhead clearances.

A combination of these routes will give vehicles access to all the planned turbine sites.

II. Wind Turbine Generator (WTG) Deliveries in the Route Evaluation Study Area

Figure 2 depicts the likely transportation routes that would be taken to deliver WTG components, beginning where the transport vehicles exit Interstate 88 and ending at the access road entrances. The routes in Figure 2 were developed after on-site inspection of intersections, grades, culverts, and other conditions that could affect the ability of WTG delivery vehicles to reach WTG sites. Figure 2 also shows the number of WTGs that would be delivered along each road segment, as well as the route for the delivery of the components from the laydown yard.

III. Existing Road Conditions

A field review of existing conditions along each transportation route and other roads in the Study Area was conducted by Fisher Associates. Data concerning road widths and type, culvert type and diameter, culvert cover and condition, electric overhead line crossings, tree overhang locations, and bridge and road load postings were collected during the field review. These data are included in Appendix A, Figures 3, 4, 5, 6, 7, and 8.

A. Bridges and Load Posting Restrictions

Existing load-restricted bridge data for the proposed approach and departure routes within the Study Area were acquired from the New York State Department of Transportation (NYSDOT) Posted Bridges online website on 4/25/2019 (https://www.dot.ny.gov/postedbridges/). In addition, Fisher drove all potential transportation routes in the Study Area to identify load-restricted bridges and/or roadways along the proposed approach and departure routes for the Project. Posted bridges have a specific weight limit in tons that is posted on a sign, whereas R-Posted bridges have no posted weight limit but cannot safely carry vehicles over legal weight limits as per NYSDOT definition. According to the NYSDOT's Posted Bridges website, there are no Posted bridges and no R-Posted bridges in the Study Area (see Figure 7).

Along the planned transport route within the Study Area, there are two bridges that will be crossed:

- State Route 8 over Susquehanna River (on State Route 8)
- State Route 8 over Peckhams Creek (on State Route 8)

If there are any changes to the potential transportation routes in the future that direct traffic over these bridges between ramps, they will be checked for adequacy with respect to loading along with horizontal width and vertical height restrictions during the Special Hauling Permit Application process with NYSDOT.

A map of existing bridges, as well as information available from the web page for the potential approach and departure routes within the Study Area, is provided in Figure 7.

Preliminary conversations with the Town of Guilford and Chenango County have occurred. Correspondence will continue to be conducted with local and County highway supervisors and followed up with meetings. Such consultations will continue throughout the Article 10 process and prior to construction. It is anticipated that the Town highway supervisor will provide information on the type, thickness, widths, and restrictions of roads within the town, as well as conditions of town road culverts.

B. Road Surfaces

As depicted in Figure 3, the road surface types in the project area are chip and seal, dirt, gravel, or asphalt. These road surface types are found in the following locations:

- Chip and seal – Miller Road,
- Dirt – Western part Crandall Road, Brownell Road,
- Asphalt surfaces – State Route 8, County Road 35, County Road 37, County Road 36, Phillips Odell Road, Blower Road, Shumway Hill Road, Whites Hill Road

C. Culvert Cover and Conditions

Within the Study Area, there are 23 small (36" diameter and smaller) and 3 large (greater than 36" diameter) culverts along the potential transportation routes. Based on the site evaluation, approximately 6 of these culverts have less than 2 feet of cover over them. It is assumed that any culvert with less than 2 feet of cover may be susceptible to damage from transportation of heavy loads during construction.

The large culverts along the potential transportation routes have been assigned a condition rating from NYSDOT and Chenango County. Visual inspections were performed on the remaining culverts consistent with the NYSDOT Culvert Inspection Field Guide summarized below:

7 – New condition. No deterioration. (Excellent)
6 – Used to shade between ratings 5 and 7.
5 – Minor deterioration but functioning as originally designed. (Good)
4 – Used to shade between ratings of 3 and 5. Functioning as originally designed.
3 – Serious deterioration or not functioning as originally designed. (Fair)
2 – Used to shade between ratings 1 and 3.
1 – Totally deteriorated or in failed condition. Potentially hazardous. (Poor)

The culvert inspections do not include load ratings or sufficiency ratings, which are typically only available for bridges. These locations will be further analyzed during final engineering to determine if improvements are necessary prior to using the routes for deliveries of construction materials. Any necessary road improvements related to the Facility as well as restoration of damaged culverts will be addressed in RUAs with the Town of Guilford and Chenango County.

Figures 4 and 5 show the location and list the size, condition, and cover for culverts under public roads within the Study Area. Most are in adequate condition and should be able to withstand Project traffic. Those that are in poor condition or are 36-inches and larger with less than 2 feet of cover could be vulnerable to damage by Project traffic if steps are not taken beforehand to improve or protect them (e.g., using steel plates). The culverts that may warrant this attention are:

- Blower Road:
  - One culvert has less than two feet of cover and is in poor condition:
    - One 12-inch HDPE culvert
- County Rd 36:
  - One culvert is in poor condition:
    - 24-inch concrete culvert
- Phillips Odell Road:
  - Two culverts have less than 2' of cover, but are in good condition:
    - Two 36-inch CMP culvert (1' of cover)

D. Overhead Clearance

Figure 6 show locations along the planned delivery route within the Study Area where overhead electric conductors or tree branches overhang the travel lanes. The typical overhead clearance required by the component delivery companies is 16', although actual heights are generally less than 15'. In either case, once the delivery height of the equipment for the Project is determined, sufficient clearance to these lines will need to be confirmed. Coordination with the local utility companies will be needed to obtain the necessary permits to raise the wires. In addition, avoidance of any tree overhangs that will be in the path of Project vehicles will need to be coordinated with the appropriate landowner.

E. Route Segment Assessment

State Route 8 provides a 24-foot wide roadway with shoulders that vary in width from 4 feet to 6 feet (see Figure 3). At some culvert locations, the shoulder width is reduced to 3 to 4 feet. The roadway terrain is rolling. There is no load posting on SR 8, so it is assumed that this roadway is adequate to handle the heavy loads associated with delivering WTGs and related construction equipment and supplies.

> **State Route 8**, Interstate 88 to Shumway Hill Road – The length of this segment is 12.2 miles. The asphalt pavement condition is rated good. The speed limit for this segment is generally 55 miles per hour (mph) with a speed reduction to 35 mph around various sharp bends. The road width is 23 to 24 feet and shoulder widths range from 2 to 6 feet. Most bridges and large culverts along this route have conforming bridge/culvert rails. The

minimum width between any bridge/culvert rails along this route is 25 feet at a location one mile north of State Route 7.

Blower Road provides a 20-foot wide roadway with shoulders that vary in width from 0 feet to 3 feet (see Figure 3). At some culvert locations, the shoulder width is reduced to 1 to 2 feet. The roadway terrain is rolling. There is no load posting on Blower Road. It is therefore recommended that this road be tested prior to construction to determine if improvements need to be made to accommodate the heavy loads associated with delivering WTGs and related construction equipment and supplies.

Blower Road, County Road 37 to Shumway Hill Road – The length of this segment is 1.8 miles. The asphalt pavement condition is rated fair. The speed limit for most of this segment is 35 mph. The road width is 20 feet and shoulder widths range from 0 to 2 feet. There is one 12" culvert along this route that is rated as Poor (totally deteriorated or in failed condition.

County Roads (CR) 35, 36, and 37 vary in width from 21 to 38 feet and have shoulders that vary from 1 foot to 6 feet wide. The roadway terrain is rolling with some roads having roadside hazards such as steep slopes and sharp bends. There are no bridges located on the county roads identified as potential transportation routes. In general, these roads have conditions rated "good," and should only require local repairs and tree clearances.

CR 35, SR 8 to CR 36 – The length of this segment is 5.6 miles. The asphalt pavement condition is rated good. The speed limit for this segment is unknown but assumed to be 55 mph based on road characteristics. The road width is 38 feet and shoulder widths range from 3 to 6 feet. There is one culvert on this section of road, and it is rating in good condition.

CR 36, CR 35 to Whites Hill Road – The length of this segment is 3.5 miles. The asphalt pavement condition is rated good. The speed limit for this segment is unknown, but is assumed to be generally 45 mph. The road width is 21 feet and shoulder widths range from 2 to 4 feet. The one culvert on this section of road is rated in poor condition. There is a flashing red traffic signal at the intersection of CR 36 and CR 37.

CR 37, CR 35 to SR 8 – The length of this segment is 5.0 miles. The asphalt pavement condition is rated good. The speed limit for this segment is unknown, but is assumed to be generally 45 mph. The road width is 21 feet and shoulder widths range from 1 to 3 feet. Most large culverts along this route have conforming bridge/culvert rails. There are no culverts rated in poor condition. Culvert conditions range from excellent (new or showing no deterioration) to fair (serious deterioration or not functioning as originally designed). There are two vertical curves that may need to be adjusted to accommodate turbine component traffic. There are traffic signals at the beginning and end of this segment of road.

Crandall Road provides a 20-foot wide roadway with shoulders that vary in width from 0 feet to 3 feet (see Figure 3) near State Route 9, then transitions to a 16-foot wide dirt road without shoulders.

At some culvert locations, the shoulder width is reduced to 1 to 2 feet. The roadway terrain is rolling. There is no load posting on Crandall Road. It is therefore recommended that this road be tested prior to construction to determine if improvements need to be made to accommodate the heavy loads associated with delivering WTGs and related construction equipment and supplies.

> **Crandall Road**, SR 8 to Brownell Road – The length of this segment is 1.6 miles. The road width is 20 feet and the asphalt pavement condition is rated poor near State Route 8 and transitions to a 16-foot wide dirt road. The speed limit for this segment is unknown but assumed to be 30 mph based on road conditions. The road width is 16 feet and composed of dirt. There is one culvert located near State Route 8 that is rated as good.

Miller Road provides a 20-foot wide roadway with shoulders that vary in width from 0 feet to 3 feet (see Figure 3). The roadway terrain consists of hills that will be investigated to determine adequacy. There is no load posting on Miller Road. It is therefore recommended that this road be tested prior to construction to determine if improvements need to be made to accommodate the heavy loads associated with delivering WTGs and related construction equipment and supplies.

> **Miller Road**, County Road 37 to Shumway Hill Road – The length of this segment is 1.3 miles. The asphalt pavement condition is rated good. The speed limit for this segment is unknown but assumed to be 35 miles per hour (mph) based on roadway conditions. The road width is 20 feet and shoulder widths range from 2 to 6 feet. There are no culverts in the area proposed to be used for transport.

Phillips Odell Road provides a 20-foot wide roadway with shoulders that vary in width from 0 feet to 3 feet (see Figure 3). The roadway terrain is rolling. There is no load posting on Phillips Odell Road. It is therefore recommended that this road be tested prior to construction to determine if improvements need to be made to accommodate the heavy loads associated with delivering WTGs and related construction equipment and supplies.

> **Phillips Odell Road**, County Road 35 to County Road 37 – The length of this segment is 2.8 miles. The asphalt pavement condition is rated good. The speed limit for this segment is not posted but assumed to be 45 mph based on roadway conditions. The road width is 21 feet. There are three culverts on this section of road rated in good condition with 1 foot of cover.

Shumway Hill Road provides a 19-foot wide roadway with shoulders that vary in width from 0 feet to 3 feet (see Figure 3). The roadway terrain is rolling and there are steeper areas that will require additional analysis. There is no load posting on Shumway Hill. It is therefore recommended that this road be tested prior to construction to determine if improvements need to be made to accommodate the heavy loads associated with delivering WTGs and related construction equipment and supplies.

> **Shumway Hill Road**, Blower Road to SR 8 – The length of this segment is 2.3 miles. The asphalt pavement condition is rated good. The speed limit for this segment is unknown but assumed to be 35 mph. The road width is 19 feet and shoulder widths range from 0 to 3

feet. Large culverts along this route have conforming bridge/culvert rails. There are two culverts along this route, one is rated as good, the other fair.

Whites Hill Road provides a 20-foot wide roadway with shoulders that vary in width from 0 feet to 3 feet (see Figure 3). The roadway terrain is rolling. There is no load posting on Whites Hill Road. It is therefore recommended that this road be tested prior to construction to determine if improvements need to be made to accommodate the heavy loads associated with delivering WTGs and related construction equipment and supplies.

Whites Hill Road, County Road 36 to Blower Road – The length of this segment is 2.1 miles. The asphalt pavement condition is rated good. The speed limit for this segment is generally 55 mph with a speed reduction to 35 mph around various sharp bends. The road width is 20 feet and shoulder widths range from 0 to 3 feet. The one culvert on this segment of road is in good condition with 1 foot of cover. There are areas of steeper terrain that will require additional investigation.

The town roads along the evaluated routes have roadway surfaces that are either asphalt, chip and seal, gravel, or dirt. The road widths range from 11 feet to 27 feet, with some roads consisting of an 11-foot single lane. The shoulder widths vary from 0 feet to 5 feet along these roads; shoulder material is asphalt, gravel, or dirt. The terrain for these roads is rolling with some steeper areas needing additional investigation. Roadside hazards are numerous and similar to those observed on county roads. Gravel roads typically have a material thickness of 5 to 6 inches. Town roads 20 feet wide or less with thin asphalt or gravel surfaces will likely require improvements to support vehicle loads during construction. The majority of town road conditions are rated "fair" and should mostly require just local repairs with some road widening and tree clearing. The exceptions to this is Crandall Road, which is rated to be in "poor" condition due to inadequate roadway width and subbase. Figure 3 includes the detail on the road material and width and a breakdown of town road widths is set forth below:

- CR 37: 21' wide
- Whites Hill Road: 20' wide
- Shumway Hill Road: 19' wide
- Miller Road: 20'wide
- Blower Road: 20' wide
- Phillip Odell Road: 18'-22' wide
- CR 36: 21' wide
- CR 35: 38' wide
- Crandall Rd: 20'-16' wide

State roads and county roads will be utilized as much as possible for construction traffic within the Study Area. Where necessary, town roads will be used as the last point of access to the wind turbine locations.

IV. Intersection Modifications

The delivery routes shown in Figure 2 would require the Project to make modifications at several intersections to accommodate the large turning radii of the WTG delivery vehicles. The intersections that would likely require modifications are shown in Figure 9 and listed in Table 1 below. Fisher modeled these intersections with truck modeling programs using a 200-foot inside radius to develop the least impactful recommendations for modifications. Detailed plans for the modifications are provided in Figure 8a – Figure 8g.

Table 1. Intersection Modifications

No.	Road 1	Road 2	Road 1 Owner	Road 2 Owner	Summary of Modifications	Utility Pole Mods Expected?
1	SR 8	CR 35	NY State	Chenango County	Infill SW corner	Yes
2	CR 35	CR 36	Chenango County	Chenango County	Infill NE corner	No
3	CR 36	CR 37	Chenango County	Chenango County	Temporary Lane on NE corner	No
4	CR 36	Whites Hill	Chenango County	t/o Guilford	Temporary Lane on SE corner	No
5	Whites Hill	Miller Road	t/o Guilford	t/o Guilford	Temporary Lane on NW corner	No
6	Old SR 8	Shumway Road	NY State	t/o Guilford	Temporary Lane on North side	No
7	SR 8	Old SR 8	NY State	NY State	Infill East corner	No

V. Project Trip Generation Characteristics

A. Number, Frequency, and Timing of Vehicle Trips

The construction of each wind turbine will require the use of approximately 11 OS/OW trucks. For the purposes of impact calculations, it is assumed that up to 25 wind turbines will be constructed. The exact construction vehicles have not yet been determined; however, it is known that the transportation of turbine components and associated construction material involves numerous conventional and specialized transportation vehicles. A summary of the types of construction vehicles that will be used to transport the turbine components and construction materials/equipment is provided below.

Wind Turbine Equipment:

- Blade Sections – Blades are transported on trailers with one blade per vehicle. Blades typically control the length of the design vehicle and the radius of the curve along the travel route to the site. Specialized transport vehicles are designed with articulating (manual or self-steering) rear axles to allow maneuverability through the curves.
- Tower Sections – Typically transported in six sections depending on the supplier. Towers generally control the height and width of the design vehicle dimensions.

- Nacelle – The nacelle and related elements are typically the heaviest component transported. Typically, one nacelle is transported per truck.
- Hub and Nose Cone – Typically transported with one or more of the same element on a vehicle. These elements are not critical elements related to design vehicle dimensions.
- Escort Vehicles – Typically a car or pick-up truck.

Construction Equipment and Materials:

- Gravel trucks with capacity of approximately 10 cubic yards (cy) per truck and estimated gross weight of 75,000 pounds (lbs.) (including anticipated truck weight) for access road construction. Currently, the total length of the access roads is approximately 62.000 feet long (12 miles) and a minimum of 20-feet wide, with gravel 12 inches deep.
- For assembly of the wind towers, cranes are transported in sections utilizing up to 16 trucks, resulting in numerous trips to the site. Assembled cranes may be crawled between tower sites or disassembled to travel along the local roads to the next site.
- Concrete trucks for construction of turbine foundations and transformer pads with a capacity of approximately 10 cy per truck and an estimated gross weight of 96,000 lbs. (including anticipated truck weight). The total amount of concrete required at each turbine location will be approximately 1400 tons depending on model and size of turbine selected.
- Variety of conventional semi-trailers for delivery of reinforcing steel (two per turbine foundation) and small substation components and interconnection facility material.
- Variety of conventional vehicles carrying water, fuels or chemicals required to construct the Project.
- If an on-site concrete batch plant is to be utilized, there will be several large trucks to deliver the equipment, as well as aggregate and cement trucks.
- For the O&M building, there will be multiple trailers to bring in the various materials to construct the building.

Trucks and cars for transporting construction workers, small equipment, and tools are not included in the above list because of their minimal impact on traffic volume and road integrity.

The following table provides estimates of the total number of trips for all heavy vehicles entering the Study Area associated with tower construction.

Table 2. Estimated Total Number of Heavy Vehicle Trips Required for Project Construction

Component/Truck Type	Assumption	Trips
Blades	**3 blades per turbine, 1 blade per truck**	**75**
Towers	**6 tower sections per turbine, 1 section per truck**	**150**
Nacelle	**1 nacelle per truck**	**25**
Hub and Nosecone	**Multiple pieces per vehicle, assume 3 per truck for each**	**25**
Road, O&M, & Laydown Yard Construction	**Gravel trucks, 10 cubic yards per truck, plus other construction equipment**	**7283**
Crane	**Several trips per access point depending on the degree of disassembly**	**88**
Concrete	**Concrete trucks, 715 cubic yards per turbine foundation, 10 cubic yards per truck. Approximately 72 trips per tower.**	**1800**
Total Heavy Vehicle Trips		**9,446**

* Note: A trip is defined as entry and exit from the Project Area

While OS/OW vehicles are traveling along the delivery route and within the Project Site, the existing traffic may experience minor delays as escort vehicles and/or flag persons stop traffic to allow safe passage. The Applicant has identified 11 routes for OS/OW vehicles transporting turbine components and supplies to the Facility Site identified as Access Routes A through K. Maps of the OS/OW access routes can be found in Figure 2. A table of construction vehicle routes/volumes is presented below.

Table 3. Construction Vehicle Volumes

Construction Routes	Gravel (Cubic Yards)	Number of Gravel Trucks	Concrete Mix (Cubic Yards)*	Number of Concrete Trucks	Number of Turbines per Access Route	Number of Turbine Delivery Trucks	Number of Crane Trucks**
Access Road A	4744	474	715	72	1	11	4
Access Road A1	963	96	715	72	1	11	4
Access Road B	1612	161	715	72	1	11	8
Access Road C	1327	133	715	72	1	11	8
Access Road D	2102	210	715	72	1	11	8
Access Road E	1356	136	715	72	1	11	8
Access Road F	5505	551	2145	216	3	33	8
Access Road G	2879	288	715	72	1	11	4
Access Road G1	898	90	715	72	1	11	4
Access Road H	2326	233	715	72	1	11	4
Access Road H1	2473	247	715	72	1	11	4
Access Road I	1479	148	715	72	1	11	8
Access Road J	2813	281	715	72	1	11	4
Access Road J1	3241	324	715	72	1	11	4
Access Road K	6684	668	2145	216	3	33	4
Access Road K1	8101	810	2860	288	4	44	4
Access Road K2	1252	125	715	72	1	11	0
Access Road K3	710	71	715	72	1	11	0
Brownell to T120	1472	147	0	0	0	0	0
Laydown / O&M	20899	2090	0	0	0	0	0
Volume Totals	72,835	7,283	17,880	1,800	25	275	88

* Concrete volume per foundation was determined as an average value of 715 cubic yards per turbine
** Number of crane trucks are 8 per assembly. In some instances, crane walks traverse multiple access roads. These totals have been split between each associated access road.

Final transportation routes cannot be determined until the turbine manufacturer has been selected. Therefore, the final transportation routes will be identified prior to Project construction. Consistent with the discussion above, when evaluating viable transportation routes for delivery of turbine components and construction materials/equipment to the Project, several items must be considered. These items are:

- The roadway characteristics and condition;
- The number of bridges along a designated route;
- The condition of the bridges and culverts that are along the route;
- The number of intersections needing turning movements;
- Number of sharp curves (to avoid additional mitigation and/or safety issues); and
- Various potential restrictions such as narrow bridges, low overhead clearances and impacts from small intersection radii affecting the turning movements.

The alternative routes are contained in Appendix A of this report. Based on this assessment, the following are recommended access routes to the various Project locations based on specific logistical concerns:

Access Route A and Access Route A1 (Turbines 101 and 102) –See Figure 1b in Appendix A of this report for the map of access route locations.

The access to these turbines is directly off of County Road 36.

Access Route B (Turbine 103) – See Figure 1b in Appendix A of this study for the map of access route location.

The access to these turbines is directly off of County Road 36.

Access Route C, Access Road D, and Access Road E (Turbines 105, 104, and 106) – See Figure 1b in Appendix A of this study for the map of access route locations.

Two alternatives are being reviewed and considered to access the turbines off of these access roads (T104, T105 and T106). The only public road access is from Whites Hill Road/Shumway Road. There is a steep portion of Whites Hill east of County Road 36 between Access Road C and Access Road D that may not be suitable for component deliveries in its current condition. There are also challenges with the routing from County Road 36 onto Whites Hill Road due to landowner status and grades. If the traffic cannot go from County Road 35 east onto Whites Hill, then all deliveries will have to come from State Route 8 west onto Shumway Hill Road.

Access Route F (Turbines 122, 123, and 124) – See Figure 1b in Appendix A of this study for the map of access route location.

The access to these turbines is directly off of County Road 37.

Access Route G and Access Route G1 (Turbines 113 and 112) – See Figure 1b in Appendix A of this study for the map of access route location.

The only viable route for access to these turbines is to come from State Route 8, west on Shumway Hill Road and north onto Miller Road. Other routes were investigated, but were dismissed due to lack of room to construct the temporary intersection improvements that would be needed.

Access Route H, H1 and Access Route I (Turbines 117, 115 and 118) – See Figure 1b in Appendix A of this study for the map of access route location.

The only viable route for access to these turbines is to utilize Access Road J from Turbine 120 to get to Brownell Road/Crandall Road. Crandall Road cannot be used from the east due to horizontal and vertical challenges to overcome to meet turbine supplier requirements. Brownell Road is off of County Road 37 is currently a private road and may have a landowner issue to resolve before it could be used.

Access Route J and Access Route J1 (Turbines 120 and 121) – See Figure 1b in Appendix A of this study for the map of access route location.

The access to these turbines is directly off of County Road 37.

Access Route K, Access Route K1, Access Route K2 and Access Route K3 (Turbines 126, 127, 128, 129, 131, 134, 135, 130, and 133) – See Figure 1b in Appendix A of this study for the map of access route location.

The access to these turbines is directly off of County Road 37.

B. Approach and Departure Routes for Trucks Carrying Water, Fuels or Chemicals

The construction of this Project will involve relatively few trucks carrying water, fuels or chemicals, particularly when compared to the construction of conventional power plants. All trucks carrying these materials during Project construction will utilize the same transportation routes used by other construction vehicles/component delivery haulers.

C. Conceptual Transportation and Approach / Departure Routes for Workers and Employees

Any workers and employees in regular vehicles (pick-up truck size and smaller) will access the construction site and worker parking areas through use of whichever public road route is most logical and efficient for the respective individual/vehicle. Employees and workers accessing the site with heavy haul/construction equipment (i.e., dump trucks or larger), or anything that exceeds the posted weight limits on public roads, will follow the final transportation routes.

VI. Traffic and Transportation Impacts

A. Overview

Once the Project is commissioned and construction activities are officially concluded, traffic associated with the Project operation will be negligible. What traffic there is will be associated with Project employees traveling to and from the O&M building and the individual turbines. Each turbine typically requires routine maintenance visits twice a year. Turbines or other Project components will require periods of more frequent service if maintenance issues arise. Service visits typically involve one to two pick-up trucks. However, because all turbines and associated access roads are located on and accessed from private land, public road use associated with routine maintenance will be limited. If major maintenance is needed (e.g., maintenance involving a crane), the language in the RUA between High Bridge Wind and the host communities will dictate the procedures followed by High Bridge Wind to ensure that any impacts to public roads are avoided or mitigated. These agreements have not been executed yet, but should be final prior to the start of construction.

B. Over-sized Deliveries

Existing roadway restrictions (height, width, weight) and deficient intersection radius locations were observed in the field and researched from NYSDOT resources during the preparation of this Route Evaluation Study. As previously noted, Fisher drove all potentially impacted roads to identify physical restrictions/hazards. In addition, the consultant used aerial imagery to analyze 200-foot radius impacts at various intersections along transportation routes. Maps of intersection turning movements on aerial imagery are included in Figure 8 of the Route Evaluation Study.

As previously discussed, transportation of the turbine blades will require use of a 155-foot trailer. Several general concerns relating to the transportation of this and other OS/OW loads were identified during the above-referenced field evaluation. Height restrictions such as overhead wires at locations throughout the Project Area (see Figure 6) will prevent or make it difficult for OS/OW vehicles to access certain sites. As discussed above, there are some local roads within the Project Area that are narrow with only one lane. Some access routes are located along these narrow roads, so it may be necessary to either widen the road or provide traffic control (i.e., a contracted flag person or a local police agency) for the OS/OW delivery vehicles. In addition, tight curves exist on some roadways. Additional widening with gravel and/or other measures will be needed in these locations to accommodate up to a 200-foot radius turn for the OS/OW delivery vehicles (see Section V above and Figure 8a – Figure 8g). Large culverts along the potential construction routes appear to have sufficient width to accommodate the OS/OW vehicles but will need to be checked during the Special Hauling Permit Application process.

Although there are no weight restrictions along State and County roads, the Town of Guilford may have local roads with load postings that are to be determined by the town highway supervisor at the time the road is needed as a transportation route.

Section V provides a table of proposed intersection improvements. A map showing the location of these improvements, and detailed figures showing anticipated intersection turning movements are

included in Figure 8 to this report. All improvements identified in Figure 8 will require verification and/or update following Certification when the final turbine supplier is identified and the final transportation routes can be determined.

C. Measures to Mitigate for Impacts to Traffic and Transportation

Measures to mitigate impacts to traffic and transportation are summarized below.

(i) Roads

Construction of the Project may necessitate road improvements to accommodate OS/OW vehicles. Along the potential access routes, road surface widths vary from approximately 10 feet to 38 feet. Roads in fair condition (Miller Road, Shumway Hill, Whites Hill, Blower Road, and Phillips Odell Road) should only require minor local repairs and tree clearing needed. All state and county roads are rated in good condition and will not require significant repairs. Some or all these roads may need to be widened or require traffic control measures to accommodate the OS/OW delivery vehicles. Radii of typical intersections (to the edge of pavement) along the potential access routes vary from approximately 25 to 200 feet. A radius of approximately 185 to 200 feet is typically necessary to accommodate the wheel paths of turbine delivery vehicles; 200 feet or more may be needed for the load clearance of these vehicles. Temporary widening of the road with an aggregate roadway surface will be required to accommodate the turning movements of turbine delivery vehicles in some locations. Further mitigation may be needed if the turbine blade extends beyond the outer trailer of the delivery vehicle. Figure 9 of this study identifies locations where these road improvements and other mitigation measures will likely be necessary.

These road improvements will be made at High Bridge Wind's expense prior to the arrival of OS/OW vehicles. Final transportation routing will not be determined until after a certificate has been issued by the Siting Board, which will allow High Bridge Wind to determine which of the turbine locations (and associated access routes) will be constructed and thus which mitigation measures, if any, must be implemented. Final transportation routing will ultimately be designed in consultation with the Town of Guilford and Chenango County highway supervisors to avoid/minimize, to the extent practical, safety issues associated with the use of the approved transportation routes, which will confine the heavy truck travel to a few select roads.

High Bridge Wind will repair damage done to roads affected by construction within the approved transportation route per the RUAs to be executed with the Town of Guilford and Chenango County prior to the start of construction, thereby restoring the affected roads to equal to or better than pre-construction conditions. Asphalt and gravel roads rated "Fair" to "Good" will be monitored during construction for pot-holing and pavement deterioration to ensure safety for general construction and local traffic. The volume and weight of both the general construction traffic and turbine delivery (OS/OW) vehicles may cause accelerated distress that could require temporary repair. These temporary repairs/improvements could include repaving with asphalt, adding gravel stone, and/or

temporary traffic signs, and may be stipulated as a condition of a RUA with local governments.

After completion of construction activities, permanent road improvements may be needed to address damage caused by the heavy construction vehicle traffic; roads needing temporary repairs during construction are most likely to need permanent repairs. RUAs may require the repair the roadways to pre-construction conditions using appropriate treatments (e.g., oil and stone, hot or cold mix asphalt, and/or additional gravel). Once a formal study is conducted, details regarding the temporary repairs, permanent road improvements, and/or mitigation measures anticipated for specific road segments will be provided in order to complete this agreement.

High Bridge Wind anticipates complying with the substantive requirements of the local laws related to road use. Any additional time restrictions for delivery of Project components will be addressed in the Host Community Agreement (HCA) and/or RUA between High Bridge Wind, the Town, and County or during construction based on input from the Town Highway Superintendent.

(ii) Culverts and Bridges

As previously discussed, a preliminary assessment of culverts, including the visual condition of the culvert itself and the amount of cover under the roadway and over the culvert, was conducted as part of the review of all potentially impacted roadways. In addition to this preliminary review, each culvert/drainage pipe will be analyzed during the final design of the roadway improvements to determine whether the amount of cover over the pipe is adequate and to identify any improvements needed to accommodate construction traffic. Necessary improvements will be addressed in the final RUA with local governments.

Preferred access routes have been selected to bypass deficient bridges and large culverts where possible to avoid additional mitigation. During the Special Hauling Permit application process, the NYSDOT and Chenango County Public Works Department will be required to review and approve all bridges and culverts to be traversed along the access routes in the construction phase.

(iii) Utilities and Traffic Control Devices

Along construction transportation routes, there are low overhead wires present that will likely need to be raised to accommodate the transport material heights of OS/OW delivery vehicles. If necessary, permits to raise the wires will be obtained through coordination with local utility companies.

No new traffic control devices are anticipated to be necessary and no damage to roads due to normal operation of the built Project are expected to occur. If any damage to local, or county roads is caused by transportation activities associated with operation of the Project, repairs will be made at High Bridge Wind's expense.

D. Road Use and Restoration Agreements

In conjunction with this Project, High Bridge Wind and/or its transportation consultant have met with Highway Superintendents from the Town of Guilford and Chenango County. In these meetings, RUAs were discussed, and all anticipated town permits required were identified. The Town and County have been provided with a copy of the HCA, which contains road use and restoration language. During these meetings, High Bridge Wind and/or its transportation consultant discussed the proposed Project, the Article 10 process, RUAs, and the general construction and transportation processes when constructing a wind farm. No major road projects or conflicting plans were identified by either of the above entities.

A variety of special hauling permits and RUAs will be required due to the large dimensions of the wind turbine components and construction cranes. The types of permits required will depend on the characteristics of the vehicle and its cargo, the number of trips, the distance traveled, and the duration. The NYSDOT Central Permit Office stipulates that when any vehicle exceeds 16 feet in width, 15'-11" in height, 160 feet in length, or 200,000 pounds in gross weight, or any combination of those, a Type 1S – Superload Trip Permit is required from NYSDOT. As some of the OS/OW vehicles used in the installation of the Project will likely exceed these metrics, High Bridge Wind will fill out and submit a PERM 12 Form – Special Hauling Pre-Approval Form for a future Type 1S – Superload Trip Permit. The NYSDOT website, www.dot.ny.gov/permits, outlines the guidelines, types and fees for various special hauling permits. Referring to the website, additional Permit Forms include the Type 1S – Superload Trip Permit such as PERM 39 – Application for Special Hauling Permit, PERM 39-1VC – Vehicle Configuration Attachment, PERM 39-4 – Additional Trailer Attachment (Option 1), PERM 99 – Additional Trailer Attachment (Option 2), PERM 85 – Special Hauling Route Survey. A Special Hauling Customer Guide is available under the PERM 30 form.

High Bridge Wind or other responsible party, such as the BOP Contractor or turbine supplier, will set up an account to complete the permit process. Highway Work Permits will be required from the respective local governments for intersection and roadway improvements within the NYSDOT (PERM 33 Form) county and town rights-of-way.

See the following Table of Roadway Agreements and Permits for a list of State, County, and Town requirements. High Bridge Wind is requesting that the Siting Board not preempt these requirements, and allow the State, County and Town to approve the listed road or highway work permits.

Table 4. Roadway Agreements and Permit Table

Agency	Road Use Agreement	Highway Work Permit to Work Within ROW	Highway Utility Permit to Work Within ROW	Special Haul Permit for Oversized/ Overweight Vehicles	Permit to Exceed Posted Weight Limit Roads	Divisible Load Overweight Permit	Contact Information
Town of Guilford	✓	✓					Highway Supervisor Bob Fleming 607-895-6816
Chenango County	✓	✓	✓	✓			Director of Highways Susan Brown 607-778-2228 bcdpwhighways @co.Chenango.ny.us
NYSDOT		✓	✓	✓	✓	✓	NYSDOT Transportation Maintenance 112 Barlow Road Binghamton NY 13904 607-775-0522

For the County and Town, RUAs are anticipated to be signed to memorialize High Bridge Wind's rights and obligations for road use and repair either as a separate agreement or as part of the HCA.

High Bridge Wind has not entered into any private road use and/or restoration agreements with landowners. High Bridge Wind anticipates that all use of private property adjacent to public roads will be allowed through its standard lease or similar easement agreement with the landowner, as opposed to a RUA.

VII. Project Impact on Mass Transit

No rail or bus mass transit systems are expected to be impacted by the proposed Project. There are several airports and airstrips located within a 30-mile radius the Study Area. Sidney Municipal Airport, Oneonta Municipal Airport, and Greater Binghamton Airport are respectively 7.55, 23.23, and 28.53 miles from the Study Area. There are no heliports within 3 miles of the Facility.

VIII. Traffic and Accident Data

Existing data on vehicle traffic volumes within the Study Area was obtained from the NYSDOT Traffic Data Viewer and Highway Data Services Website. This data is summarized in Appendix B. The state and county roads have Annual Average Daily Traffic (AADT) data; local town roads do not have any published traffic volume data. The roads in the Study Area appear to operate below

vehicle capacity. A detailed capacity analysis was not completed for this Study. However, field observation of the transportation network did not reveal any locations where traffic flow and/or capacity appeared to create undue delay for the traveling public.

The table below summarizes the traffic conditions specific to the segments of the State and County roads that are within the Study Area.

Table 5. Traffic Conditions

Roadway Name	Lanes	Roadway Widths	AADT*
County Road 37	2	21’	559**
Whites Hill Road	2	19’	N/A
Shumway Road	2	19’	N/A
Miller Road	2	17’	N/A
Crandall Rd	2	10’-16’	N/A
Phillip Odell Rd	2	18’-22’	N/A
State Route 8	2	38’	3169**
County Road 36	2	21’	1657**
County Road 35	2	38’	2478**

* AADT = Average Annual Daily Trips
** Traffic volumes for transportation route were obtained from the Traffic Data Viewer website on 4/30/19.

A Freedom of Information Law (FOIL) request was submitted to the NYSDOT Region 9 in Binghamton on 5/16/18 for information on accident data in the Town of Guilford. The existing accident data from the timeframe between March 12, 2013 and February 28, 2018 was analyzed specifically along the transport route for distinct sections of each road.

County Road 37, from County Road 36 to State Route 8 (5.0 mi.), had 19 total accidents within a 5-year period, with 12 caused by deer or wet/snowy surfaces. The other seven accidents involved drivers colliding with guide rails or earth/ditch, traveling at an unsafe speed or alcohol. The road’s average accident rate is 3.72 accidents/million vehicle miles, which is above the statewide average of 2.10 accidents/million vehicle miles.

Because the majority of accidents that occurred are due to deer, wet surfaces, or driver negligence, there should be very little concern for potential accidents due to existing road or intersection conditions along this section of County Road 37 in the Town of Guilford.

Whites Hill Road, from County Road 36 to Blower Road (2.1 mi.), had four total accidents within a 5-year period, with three caused by a collision with a deer or by a deer’s actions and one due to driver inattention and unsafe speed. The road’s average accident rate is 3.42 accidents/million vehicle miles, which is above the statewide average of 2.1 accidents/million vehicle miles.

Because the accidents that occurred are due to deer or driver negligence, there should be very little concern for potential accidents due to existing road or intersection conditions along this section of Whites Hill Road in the Town of Guilford.

Shumway Hill Road, from Blower Road to State Route 8 (2.4 mi.), had two accidents within a 5-year period. The road's average accident rate is 1.50 accidents/million vehicle miles, which is below the statewide average of 2.1 accidents/million vehicle miles.

Because there were only two accidents that occurred on this section of roadway, one of which being due to deer, and due to the short length of the roadway, there should be little concern for an increase in accidents due to construction activities.

Miller Road, from Whites Hill Road to CR 33 (1.3 mi.), had three accidents within a 5-year period, with two caused by a collision with a deer. Since the AADT for Miller Road was not listed in the Traffic Data Viewer website, this section of road's average accident rate is not provided.

Because the majority of accidents that occurred are due to deer, and there is no other data to analyze, no additional analysis can be performed to determine whether an increase in traffic accidents due to construction traffic would be anticipated.

Blower Road from County Road 37 to Whites Hill Road (1.8 mi.), had one accident within a 5-year period, which was caused by driver inattention. Since the AADT for Blower Road was not listed in the Traffic Data Viewer website, this section of road's average accident rate is not provided.

Because there was only one accident that occurred on this section of roadway, and due to the short length of the roadway, there should be little concern for an increase in accidents due to construction activities.

Phillip Odell Road, from County Road 35 to County Road 37 (2.8 mi.), had zero accidents within a 5-year period. Since the AADT for Phillip Odell Road was not listed in the Traffic Data Viewer website, this section of road's average accident rate is not provided.

Because of the lack of the accidents, there should be very little concern for potential accidents due to existing road or intersection conditions along Phillip Odell Road in the Town of Guilford.

County Road 36, from County Road 35 to Whites Hill Road (3.5 mi.), had two accidents within a 5-year period, one caused by a deer and one by wet surfaces. The road's average accident rate is 0.40 accidents/million vehicle miles, which is below the statewide average of 2.1 accidents/million vehicle miles.

Because the accidents that occurred were due to deer or wet surfaces, there should be very little concern for potential accidents due to existing road or intersection conditions.

County Road 35, from State Route 8 to County Road 36 (5.6 mi.), had one accident within a 5-year period, which was caused by a wet/snowy surface. The road's average accident rate is 0.20

accidents/million vehicle miles, which is significantly less than the statewide average of 2.1 accidents/million vehicle miles.

Because the very minor number of accidents (one over a 5-year period) and the cause of the accident (wet/snowy surface), there should be very little concern for potential accidents due to existing road or intersection conditions along this section of County Road 35.

Crandall Road, from State Road 8 to the end (1.6 mi.), had were zero accidents reported in a 5-year period on this section of road. Since the AADT for Crandall Road was not listed in the Traffic Data Viewer website, this section of road's average accident rate is not provided.

Because there were no accidents that occurred on this section of roadway, and due to the short length of the roadway, no analysis can be performed to determine whether an increase in traffic accidents due to construction traffic would be anticipated.

IX. School District Bus Routes and Emergency Service Providers

The possible transportation roads needed for delivery trucks and construction vehicles travel through the Bainbridge-Guilford Central School District and the Gilbertsville – Mt. Upton School District.

As per information provided by the Bainbridge-Guilford Central School District web page, the district has buses operating on two routes that are in the Project Area. The first is on County Road 37 between 6:47 am and 6:55 am and between 3:45 pm and 4:18 pm. The second is on County Road 36 and Whites Hill Road between 6:30 am and 6:43 am and between 3:45 pm and 4:12 pm.

The Gilbertsville – Mt. Upton Central School District was contacted several times, but no information has been received from them at this time. This information will be updated as it becomes available.

The locations of emergency service provider stations near the Project including the Mt. Upton Police Department, Oxford Village Police Department, Oxford Fire Department, Unadilla Fire Department, Sidney Police Department, Village of Sidney Fire Department, and Air Methods Corporation have been mapped on Figure 9. This map of all emergency service provider locations will be posted in the Project's O&M building (and provided to the emergency service providers) and all turbines will have a unique 911 ID/address.

Each of the service providers were contacted, and those that gave a response indicated that there were no planned routes in the Project Area for emergency vehicles and that they utilize whatever route is necessary.

Appendix A

FISHER ASSOCIATES

FIGURE 1a: PROJECT LOCATION
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



Roads

- Local Road
- County Route
- State Highway
- Interstate Highway
- Study Area

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/30/2019

Map Author: MFA

0 3,000 6,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_1a_Location_Map_High_Bridge.mxd - 1:30:36 PM

FISHER ASSOCIATES

FIGURE 1b: PROJECT LAYOUT
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



Proposed Turbine
Proposed Access Road
Local Road
County Route
State Highway
Interstate Highway
Facility
Towns

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/30/2019

Map Author: MFA

0 2,500 5,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

Service Layer Credits:

H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_1b_Project_Layout_High_Bridge.mxd

FISHER ASSOCIATES

FIGURE 2: TRANSPORT ROUTES
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



Proposed Turbine
Proposed Access Road
Transportation Route (# of Turbines on Route)
Local Road
County Route
State Highway
Interstate Highway
Facility
Project Boundary
Towns

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/31/2019 | Map Author: MFA

0 3,000 6,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

Service Layer Credits:

H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_2_Transportation_Routes_High_Bridge.mxd

FISHER ASSOCIATES

FIGURE 3: ROAD WIDTH AND TYPE
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



Service Layer Credits:

Proposed Turbine
Proposed Access Road
Local Road
County Route
State Highway
Interstate Highway
Facility
Towns

Road Width & Surface

Asphalt
Dirt
Road Width Less Than 16'

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/31/2019 | Map Author: MFA

0 3,000 6,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

FISHER ASSOCIATES

FIGURE 4: CULVERT TYPE AND DIAMETER
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



Culvert
Shallow Coverage
Proposed Turbine
Proposed Access Road
Local Road
County Route
State Highway
Interstate Highway
Facility
Towns

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/31/2019

Map Author: MFA

0 2,000 4,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

Service Layer Credits:

H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_4_Culvert_Type_Diameter_High_Bridge.mxd

FISHER ASSOCIATES

FIGURE 5: CULVERT COVER AND CONDITION
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



Culvert
Poor Condition
Proposed Turbine
Proposed Access Road
Local Road
County Route
State Highway
Interstate Highway
Facility
Towns

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/31/2019

Map Author: MFA

0 2,000 4,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

Service Layer Credits:

H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_5_Culvert_Cover_Condition_High_Bridge.mxd

FISHER ASSOCIATES

FIGURE 6: OVERHEAD CROSSINGS
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



- Overhead Tree Crossing (>15')
- Overhead Electric Crossing (<=15')
- Overhead Electric Crossing (>15')
- Proposed Turbine
- Proposed Access Road
- Local Road
- County Route
- State Highway
- Interstate Highway
- Facility
- Towns

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/31/2019

Map Author: MFA

0 3,000 6,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_6_Overhead_Crossing_High_Bridge.mxd

FISHER ASSOCIATES

FIGURE 7: LOAD POSTING
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_7_Load_Postings_High_Bridge.mxd

Service Layer Credits:

NYSDOT Bridge
County Bridge
Town Bridge
Proposed Turbine
Proposed Access Road
Local Road
County Route
State Highway
Interstate Highway
Facility
Towns

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/31/2019

Map Author: MFA

0 3,000 6,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

FISHER ASSOCIATES

FIGURE 8: INTERSECTION IMPROVEMENTS
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



Public Road Intersection Improvement
Proposed Turbine
Proposed Access Road
Local Road
County Route
State Highway
Interstate Highway
Facility
Towns

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/31/2019

Map Author: MFA

0 3,000 6,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_8_Intersection_Improvements_High_Bridge.mxd

Service Layer Credits:

PROJECT

HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NEW YORK
PUBLIC ROAD INTERSECTION IMPROVEMENTS

COPYRIGHT © 2019
FISHER ASSOCIATES, ENGINEERS, P.C.

New York State Education Law Section 7209 states that it is a violation of this law for any person, unless he/she is acting under the direction of a licensed professional engineer or land surveyor, to alter an item in any way.

If an item bearing the seal of an engineer or land surveyor is altered, the altering engineer or land surveyor shall affix to the item his/her seal and the notation "altered by" followed by his/her signature and the date of such alteration, and a specific description of the alteration.

TITLE OF DRAWING

INTERSECTION IMPROVEMENT #1- NYS ROUTE 8 TO COUNTY ROAD 35

DRAWING NO.	ISSUE DATE:	DRAWN BY:
FIGURE 8A	JULY 2019	CH
FA PROJECT NO.	SCALE:	CHECKED BY:
185048	1"=50'	LO

FISHER ASSOCIATES

WWW.FISHERASSOC.COM

FILE NAME: H:\Projects\185048-00-High_Bridge_Wind\Eng\CAD\CUT\public road improvements - exhibits\185048 - intersection improvement exhibits.dwg
DATE/TIME: 7/30/2019 10:11:47 AM
USER: Jacob Remington

PROJECT

HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NEW YORK
PUBLIC ROAD INTERSECTION IMPROVEMENTS

COPYRIGHT © 2019
FISHER ASSOCIATES, ENGINEERS, P.C.

New York State Education Law Section 7209 states that it is a violation of this law for any person, unless he/she is acting under the direction of a licensed professional engineer or land surveyor, to alter an item in any way.

If an item bearing the seal of an engineer or land surveyor is altered, the altering engineer or land surveyor shall affix to the item his/her seal and the notation "altered by" followed by his/her signature and the date of such alteration, and a specific description of the alteration.

TITLE OF DRAWING

INTERSECTION IMPROVEMENT #2- COUNTY ROUTE 35 TO COUNTY ROAD 36

DRAWING NO.	ISSUE DATE:	DRAWN BY:
FIGURE 8B	JULY 2019	CH
FA PROJECT NO.	SCALE:	CHECKED BY:
185048	1"=50'	LO

FISHER ASSOCIATES

WWW.FISHERASSOC.COM

FILE NAME: H:\Projects\185048-00-High_Bridge_Wind\Eng\CAD\CUT\public road improvements - exhibits\185048 - intersection improvement exhibits.dwg
DATE/TIME: 7/30/2019 10:33:07 AM
USER: Jacob Remington

PROJECT

HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NEW YORK
PUBLIC ROAD INTERSECTION IMPROVEMENTS

COPYRIGHT © 2019
FISHER ASSOCIATES, ENGINEERS, P.C.

New York State Education Law Section 7209 states that it is a violation of this law for any person, unless he/she is acting under the direction of a licensed professional engineer or land surveyor, to alter an item in any way.

If an item bearing the seal of an engineer or land surveyor is altered, the altering engineer or land surveyor shall affix to the item his/her seal and the notation "altered by" followed by his/her signature and the date of such alteration, and a specific description of the alteration.

TITLE OF DRAWING

INTERSECTION IMPROVEMENT #3- COUNTY ROUTE 36 TO COUNTY ROAD 37

DRAWING NO.	ISSUE DATE:	DRAWN BY:
FIGURE 8C	JULY 2019	CH
FA PROJECT NO.	SCALE:	CHECKED BY:
185048	1"=100'	LO

FISHER ASSOCIATES

WWW.FISHERASSOC.COM

FILE NAME: H:\Projects\185048-00-High_Bridge_Wind\Eng\CAD\CUT\public road improvements - exhibits\185048 - intersection improvement exhibits.dwg
DATE/TIME: 7/30/2019 10:13:14 AM
USER: Jacob Remington

PROJECT

HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NEW YORK
PUBLIC ROAD INTERSECTION IMPROVEMENTS

COPYRIGHT © 2019
FISHER ASSOCIATES, ENGINEERS, P.C.

New York State Education Law Section 7209 states that it is a violation of this law for any person, unless he/she is acting under the direction of a licensed professional engineer or land surveyor, to alter an item in any way.

If an item bearing the seal of an engineer or land surveyor is altered, the altering engineer or land surveyor shall affix to the item his/her seal and the notation "altered by" followed by his/her signature and the date of such alteration, and a specific description of the alteration.

TITLE OF DRAWING

INTERSECTION IMPROVEMENT #4- COUNTY ROUTE 36 TO WHITES HILL ROAD

DRAWING NO.	ISSUE DATE:	DRAWN BY:
FIGURE 8D	JULY 2019	CH
FA PROJECT NO.	SCALE:	CHECKED BY:
185048	1"=50'	LO

FISHER ASSOCIATES

WWW.FISHERASSOC.COM

FILE NAME: H:\Projects\185048-00-High_Bridge_Wind\Eng\CAD\CUT\public road improvements - exhibits\185048 - intersection improvement exhibits.dwg
DATE/TIME: 7/30/2019 10:13:38 AM
USER: Jacob Remington



PROJECT

HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NEW YORK
PUBLIC ROAD INTERSECTION IMPROVEMENTS

COPYRIGHT © 2019
FISHER ASSOCIATES, ENGINEERS, P.C.

New York State Education Law Section 7209 states that it is a violation of this law for any person, unless he/she is acting under the direction of a licensed professional engineer or land surveyor, to alter an item in any way.

If an item bearing the seal of an engineer or land surveyor is altered, the altering engineer or land surveyor shall affix to the item his/her seal and the notation "altered by" followed by his/her signature and the date of such alteration, and a specific description of the alteration.

TITLE OF DRAWING

INTERSECTION IMPROVEMENT #5- SHUMWAY ROAD TO MILLER ROAD

DRAWING NO.	ISSUE DATE:	DRAWN BY:
FIGURE 8E	JULY 2019	CH
FA PROJECT NO.	SCALE:	CHECKED BY:
185048	1"=100'	LO

FISHER ASSOCIATES

WWW.FISHERASSOC.COM

FILE NAME: H:\Projects\185048-00-High_Bridge_Wind\Eng\CAD\CUT\public road improvements - exhibits\185048 - intersection improvement exhibits.dwg
DATE/TIME: 7/30/2019 10:14:24 AM
USER: Jacob Remington



PROJECT

HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NEW YORK
PUBLIC ROAD INTERSECTION IMPROVEMENTS

COPYRIGHT © 2019
FISHER ASSOCIATES, ENGINEERS, P.C.

New York State Education Law Section 7209 states that it is a violation of this law for any person, unless he/she is acting under the direction of a licensed professional engineer or land surveyor, to alter an item in any way.

If an item bearing the seal of an engineer or land surveyor is altered, the altering engineer or land surveyor shall affix to the item his/her seal and the notation "altered by" followed by his/her signature and the date of such alteration, and a specific description of the alteration.

TITLE OF DRAWING

INTERSECTION IMPROVEMENT #6- OLD STATE ROUTE 8 TO SHUMWAY ROAD

DRAWING NO.	ISSUE DATE:	DRAWN BY:
FIGURE 8F	JULY 2019	CH
FA PROJECT NO.	SCALE:	CHECKED BY:
185048	1"=100'	LO

FISHER ASSOCIATES

WWW.FISHERASSOC.COM

FILE NAME: H:\Projects\185048-00-High_Bridge_Wind\Eng\CAD\CUT\public road improvements - exhibits\185048 - intersection improvement exhibits.dwg
DATE/TIME: 7/30/2019 10:28:35 AM
USER: Jacob Remington

PROJECT

HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NEW YORK
PUBLIC ROAD INTERSECTION IMPROVEMENTS

COPYRIGHT © 2019
FISHER ASSOCIATES, ENGINEERS, P.C.

New York State Education Law Section 7209 states that it is a violation of this law for any person, unless he/she is acting under the direction of a licensed professional engineer or land surveyor, to alter an item in any way.

If an item bearing the seal of an engineer or land surveyor is altered, the altering engineer or land surveyor shall affix to the item his/her seal and the notation "altered by" followed by his/her signature and the date of such alteration, and a specific description of the alteration.

TITLE OF DRAWING

INTERSECTION IMPROVEMENT #7- NYS ROUTE 8 TO COUNTY ROAD 35

DRAWING NO.	ISSUE DATE:	DRAWN BY:
FIGURE 8G	JULY 2019	CH
FA PROJECT NO.	SCALE:	CHECKED BY:
185048	1"=50'	LO

FISHER ASSOCIATES

WWW.FISHERASSOC.COM

FILE NAME: H:\Projects\185048-00-High_Bridge_Wind\Eng\CAD\CUT\public road improvements - exhibits\185048 - intersection improvement exhibits.dwg
DATE/TIME: 7/30/2019 10:29:15 AM
USER: Jacob Remington

FISHER ASSOCIATES

FIGURE 9: EMERGENCY SERVICES
HIGH BRIDGE WIND PROJECT
CHENANGO COUNTY, NY



Ambulance
Fire Department
Police
Proposed Turbine
Proposed Access Road
Local Road
County Route
State Highway
Interstate Highway
Facility
Towns

Project USGS Quad(s):

Gilford, Sidney

Map Revision Date: 7/31/2019

Map Author: MFA

0 3,500 7,000 Feet



Data Sources:

Roads NYSDOT: Accident Location Information System 2013

Service Layer Credits:

H:\Projects\185020-00-High_Bridge_Wind_Farm\GIS\Figure_9_Emergency_Services_High_Bridge.mxd

Appendix B


https://alis.dot.ny.gov/sqra/sqra/
Query and Reporting Appli...
File Edit View Favorites Tools Help
Share Browser WebEx
Google Suggested Sites
Check Status
Schedule
Load Results
Delete
Copy
Build path for corridor analysis using these tools.
Load Cases (SQR)
Perform Analysis
Query Management
Simple Query Results
Feature Selection
Build Path
Draw
Maint.
Streets
Topo
Imagery
Attribute Query - 15822
Gilbertsville
Oxford
Guilford
Wells Bridge
Unadilla
Sidney
Bainbridge
Sidney Center
4km
2mi
QRA
Overview Map

Accident Location Information System(ALIS)

Date:
3/12/2019
11:31:35 AM

Accident Verbal Description

15822_VDR

Date in this report covers the period -11/1/2013-10/31/2018

Complete Accident data from NYSDMV is only available thru 10/31/2018 12:00:00 AM

County: Chenango Muni: Guilford(T) Ref. Marker: Street: MILLER RD
179 Meters South of Miller Shumway Rd

11/27/2013 Wed 20:32 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2013-35021914**

Accident Class: NON-REPORTABLE Police Agency: NORWICH SP Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE

Manner of Collision: RIGHT ANGLE Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT AT HILLCREST Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 24 Sex: M Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 35 Sex: M Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: OVERTAKING

Apparent Factors: UNSAFE LANE CHANGE, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: WHITES HILL RD

11/25/2013 Mon 12:15 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2013-35021926**

Accident Class: NON-REPORTABLE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: MD
Num of Occupants: 1 Driver's Age: 24 Sex: M Citation Issued: N
Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
365 Meters South of Whites Hill Rd

12/7/2013 Sat 17:51 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2013-35032534**
Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1
Type Of Accident: COLLISION WITH DEER Traffic Control: NONE
Manner of Collision: OTHER Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: FL
Num of Occupants: 2 Driver's Age: 58 Sex: M Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Norwich(T) Ref. Marker: Street: MILLER SHUMWAY RD

12/9/2013 Mon 16:35 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2013-35039009**
Accident Class: PROPERTY DAMAGE Police Agency: CHENANGO CO SO Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE
Manner of Collision: RIGHT TURN (WITH OTHER CAR) Weather: CLOUDY
Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DUSK
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 BUS Registered Weight: 40 State of Registration: NY
Num of Occupants: 3 Driver's Age: 56 Sex: F Citation Issued: N
Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 2396 State of Registration: NY
Num of Occupants: 1 Driver's Age: 21 Sex: M Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING RIGHT TURN

Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, VIEW OBSTRUCTED/LIMITED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35
62 Meters East of Marble Rd

12/18/2013 Wed 17:35 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2013-35062615**

Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3279 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 64 | Sex: M | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
751 Meters South of Whites Hill Rd

12/13/2013 Fri 14:30 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2013-35075002**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH OTHER FIXED OBJECT | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 4210 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 21 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
30 Meters East of County Road 36

12/31/2013 Tue 14:30 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2013-35075009**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: SNOW/ICE | Road Char.: CURVE AND GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 4225 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 25 | Sex: F | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031025 Street: STATE HIGHWAY 8
135 Meters South of Old State Highway 8 S

1/24/2014 Fri 18:05 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2014-35106432**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: OTHER

Manner of Collision: OVERTAKING | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 OTHER | Registered Weight: | State of Registration:

Num of Occupants: 1 | Driver's Age: | Sex: U | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE LANE CHANGE, PASSING OR LANE USAGE IMPROPERLY

Veh :2 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 53 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: OVERTAKING

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH County Road 36

2/9/2014 Sun 22:27 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2014-35134412**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: YIELD SIGN

Manner of Collision: RIGHT ANGLE | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: CURVE AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 6200 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 47 | Sex: M | Citation Issued: Y

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: PAVEMENT SLIPPERY, FAILURE TO YIELD RIGHT OF WAY

Veh :2 CAR/VAN/PICKUP | Registered Weight: 3465 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 30 | Sex: F | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH County Road 36

3/3/2014 Mon 15:39 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2014-35163094**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NORWICH SP | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: REAR END | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2557 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 62 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 2918 State of Registration: NY

Num of Occupants: 1 Driver's Age: 68 Sex: M Citation Issued: Y

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FOLLOWING TOO CLOSELY, GLARE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031030 Street: STATE HIGHWAY 8

3/11/2014 Tue 08:39 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2014-35189610**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NO PASSING ZONE

Manner of Collision: REAR END Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 2 Driver's Age: 39 Sex: F Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 60 Sex: F Citation Issued: Y

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: BACKING

Apparent Factors: BACKING UNSAFELY, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

3/24/2014 Mon 15:47 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2014-35193622**

Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3100 State of Registration: NY

Num of Occupants: 1 Driver's Age: 47 Sex: F Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031091 Street: [Route] 8

4/4/2014 Fri 18:00 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2014-35216234**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: RAIN

Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 4 Driver's Age: 29 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031014 Street: STATE HIGHWAY 8
172 Meters South of County Road 35

5/31/2014 Sat 21:00 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2014-35277411**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3223 State of Registration: NY

Num of Occupants: 1 Driver's Age: 60 Sex: F Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031023 Street: STATE HIGHWAY 8
154 Meters North of Unnamed Street

6/9/2014 Mon 10:48 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2014-35283416**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 88 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031062 Street: STATE HIGHWAY 8
281 Meters West of Hazy Ridge Ln

6/8/2014 Sun 21:30 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2014-35283422**
Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2715 | State of Registration: NY
Num of Occupants: 2 | Driver's Age: 27 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031018 Street: STATE HIGHWAY 8
673 Meters South of Unnamed Street

6/2/2014 Mon 20:56 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2014-35286476**
Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DUSK

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 5 Driver's Age: 25 Sex: F Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031045 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Hitching Post Ln

6/11/2014 Wed 21:11 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2014-35288332**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH TREE | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 TRUCK Registered Weight: State of Registration: WI

Num of Occupants: 2 Driver's Age: 50 Sex: M Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: OBSTRUCTION/DEBRIS, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
43 Meters East of County Road 36

6/27/2014 Fri 13:30 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2014-35315871**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: CURVE AND GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3893 State of Registration: NY

Num of Occupants: 1 Driver's Age: 21 Sex: F Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, UNKNOWN

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031039 Street: STATE HIGHWAY 8
392 Meters South of Rockdale Rd

8/1/2014 Fri 15:56 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2014-35346933**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NONE

Manner of Collision: REAR END | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: | State of Registration: PA

Num of Occupants: 1 | Driver's Age: 46 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 21 | Sex: M | Citation Issued: Y

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FOLLOWING TOO CLOSELY, DRIVER INEXPERIENCE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
110 Meters North of Rockdale Rd

8/22/2014 Fri 01:15 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2014-35374143**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 51 | Sex: M | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING RIGHT TURN

Apparent Factors: ALCOHOL INVOLVEMENT, UNSAFE LANE CHANGE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
88 Meters North of Whites Hill Rd

9/2/2014 Tue 15:08 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2014-35385576**

Accident Class: INJURY Police Agency: NYSP SIDNEY Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: STOP SIGN

Manner of Collision: RIGHT ANGLE Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 OTHER Registered Weight: State of Registration: NY

Num of Occupants: 0 Driver's Age: Sex: Citation Issued:

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 3430 State of Registration: NY

Num of Occupants: 2 Driver's Age: 47 Sex: F Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
70 Meters East of Gonzer Rd

9/16/2014 Tue 14:54 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2014-35403368**

Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NYSP SIDNEY Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NO PASSING ZONE

Manner of Collision: LEFT TURN (AGAINST OTHER CAR) Weather: CLOUDY

Road Surface Condition: DRY Road Char.: STRAIGHT AT HILLCREST Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 2939 State of Registration: NY

Num of Occupants: 1 Driver's Age: 26 Sex: M Citation Issued: N

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2965 State of Registration: NY
Num of Occupants: 1 Driver's Age: 62 Sex: F Citation Issued: Y
Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: MAKING LEFT TURN
Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, TURNING IMPROPER

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031015 Street: STATE HIGHWAY 8
AT INTERSECTION WITH County Road 35

10/16/2014 Thu 16:19 PM Persons Killed: 0 Persons Injured: 1 Extent of Injuries: A **Case: 2014-35437379**
Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NYSP SIDNEY Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: FLASHING LIGHT
Manner of Collision: HEAD ON Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 4101 State of Registration: NY
Num of Occupants: 2 Driver's Age: 29 Sex: F Citation Issued: N
Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3972 State of Registration: NY
Num of Occupants: 1 Driver's Age: 19 Sex: M Citation Issued: Y
Direction of Travel: NORTH-WEST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: MAKING LEFT TURN
Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
1037 Meters South of Whites Hill Rd

11/26/2014 Wed 11:29 AM Persons Killed: 0 Persons Injured: 1 Extent of Injuries: C **Case: 2014-35489291**
Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: CHENANGO CO SO Num of Veh: 1
Type Of Accident: COLLISION WITH TREE Traffic Control: NONE
Manner of Collision: OTHER Weather: SNOW
Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3893 State of Registration: NY

Num of Occupants: 1 Driver's Age: 34 Sex: F Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031026 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Old State Highway 8 S

11/19/2014 Wed 18:28 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2014-35490145**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 5500 State of Registration: NY

Num of Occupants: 1 Driver's Age: 27 Sex: M Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH Phillip Odell Rd

11/17/2014 Mon 17:27 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2014-35535192**

Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: RAIN

Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3360 State of Registration: NY

Num of Occupants: 3 Driver's Age: 67 Sex: F Citation Issued: N

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT ENTERED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: BLOWER RD
AT INTERSECTION WITH Miller Rd

1/5/2015 Mon 13:22 PM Persons Killed: 0 Persons Injured: 2 Extent of Injuries: BC **Case: 2015-35558127**

Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NORWICH SP Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: STOP SIGN

Manner of Collision: RIGHT ANGLE Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 3762 State of Registration: NY

Num of Occupants: 2 Driver's Age: 43 Sex: F Citation Issued: N

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 35 Sex: F Citation Issued: Y

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: DRIVER INATTENTION, TRAFFIC CONTROL DEVICES DISREGARDED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: WHITES HILL RD
AT INTERSECTION WITH Miller Rd

1/5/2015 Mon 13:30 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35558133**

Accident Class: NON-REPORTABLE Police Agency: NORWICH SP Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE

Manner of Collision: REAR END Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 18 Sex: M Citation Issued: Y

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: UNSAFE SPEED, DRIVER INATTENTION

Veh :2 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 3 Driver's Age: Sex: Citation Issued:
Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: PARKED
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
AT INTERSECTION WITH WAHLBERG RD

1/11/2015 Sun 16:57 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35570345**
Accident Class: PROPERTY DAMAGE Police Agency: CHENANGO CO SO Num of Veh: 1
Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NONE
Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: WET Road Char.: STRAIGHT/ GRADE Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3351 State of Registration: NY
Num of Occupants: 2 Driver's Age: 20 Sex: M Citation Issued: N
Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 37
14 Meters East of Driveway

10/15/2014 Wed 07:50 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2014-35593366**
Accident Class: PROPERTY DAMAGE Police Agency: Num of Veh: 1
Type Of Accident: COLLISION WITH CURBING Traffic Control: NONE
Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: DRY Road Char.: CURVE AND GRADE Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3209 State of Registration: NY
Num of Occupants: 1 Driver's Age: 47 Sex: F Citation Issued: N
Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: AVOIDING OBJECT IN ROADWAY
Apparent Factors: NOT ENTERED, NOT ENTERED

County: Chenango Muni: Norwich(T) Ref. Marker: Street: [Route] 33
AT INTERSECTION WITH MILLER SHUMWAY RD

1/26/2015 Mon 15:20 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35599266**

Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NONE

Manner of Collision: SIDESWIPE | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: CURVE AND GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 3040 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 21 | Sex: M | Citation Issued: Y

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO KEEP RIGHT, UNSAFE SPEED

Veh :1 CAR/VAN/PICKUP | Registered Weight: 4458 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 45 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031015 Street: STATE HIGHWAY 8
AT INTERSECTION WITH County Road 35

2/18/2015 Wed 12:20 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: B | **Case: 2015-35619335**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: FLASHING LIGHT

Manner of Collision: RIGHT ANGLE | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 3988 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 75 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2925 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 20 | Sex: F | Citation Issued: Y

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: TRAFFIC CONTROL DEVICES DISREGARDED, FAILURE TO YIELD RIGHT OF WAY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 37
14 Meters East of Driveway

2/19/2015 Thu 00:45 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35621522**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL | Traffic Control: NONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 20 | Sex: F | Citation Issued: Y

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, ALCOHOL INVOLVEMENT

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
1293 Meters South of Whites Hill Rd

3/15/2015 Sun 16:09 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35656284**

Accident Class: NON-REPORTABLE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 3 | Driver's Age: 45 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031031 Street: STATE HIGHWAY 8
158 Meters South of Old State Highway 8 S

3/21/2015 Sat 08:02 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35658689**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: TN

Num of Occupants: 1 | Driver's Age: 72 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031021 Street: STATE HIGHWAY 8
265 Meters South of Unnamed Street

3/21/2015 Sat 10:07 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35658698**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 65 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
674 Meters West of Mount Upton St

3/26/2015 Thu 00:30 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35667670**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH SIGN POST | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4023 State of Registration: NY

Num of Occupants: 1 Driver's Age: 57 Sex: M Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031012 Street: STATE HIGHWAY 8
193 Meters North of Old County Road 43

3/28/2015 Sat 20:23 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35667696**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 5634 State of Registration: NY

Num of Occupants: 3 Driver's Age: 50 Sex: M Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031092 Street: STATE HIGHWAY 8

3/29/2015 Sun 19:22 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35669335**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DUSK

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 TRUCK Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 23 Sex: M Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
AT INTERSECTION WITH Whites Hill Rd

3/20/2015 Fri 18:00 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2015-35677444**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NORWICH SP | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: STOP SIGN

Manner of Collision: RIGHT ANGLE | Weather: CLOUDY

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT AT HILLCREST | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3410 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 30 | Sex: M | Citation Issued: Y

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: UNSAFE SPEED, TRAFFIC CONTROL DEVICES DISREGARDED

Veh :2 CAR/VAN/PICKUP | Registered Weight: 2294 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 32 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
AT INTERSECTION WITH N Pond Rd

4/5/2015 Sun 13:41 PM | Persons Killed: 0 | Persons Injured: 4 | Extent of Injuries: CCCC | **Case: 2015-35684199**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NORWICH SP | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: STOP SIGN

Manner of Collision: RIGHT ANGLE | Weather: SNOW

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 4389 | State of Registration: NY

Num of Occupants: 4 | Driver's Age: 72 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: STARTING FROM PARKING

Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, VIEW OBSTRUCTED/LIMITED

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 26 Sex: M Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031088 Street: STATE HIGHWAY 8
922 Meters North of Mill St

4/1/2015 Wed 12:00 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35710559**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH FENCE Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 20 Sex: M Citation Issued: Y

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, PASSING OR LANE USAGE IMPROPERLY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
172 Meters North of N Pond Rd

5/9/2015 Sat 09:30 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35722219**

Accident Class: NON-REPORTABLE Police Agency: CHENANGO CO SO Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 19 Sex: F Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: DRIVER INATTENTION, FAILURE TO KEEP RIGHT

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031081 Street: [Route] 8
AT INTERSECTION WITH [Route] 37

5/28/2015 Thu 15:30 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35749019**

Accident Class: PROPERTY DAMAGE Police Agency: CHENANGO CO SO Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: FLASHING LIGHT

Manner of Collision: RIGHT ANGLE Weather: CLOUDY

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3615 State of Registration: NY

Num of Occupants: 1 Driver's Age: 63 Sex: M Citation Issued: Y

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, NOT APPLICABLE

Veh :2 TRUCK Registered Weight: 11030 State of Registration: NY

Num of Occupants: 1 Driver's Age: 52 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

6/4/2015 Thu 21:12 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35750189**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 3 Driver's Age: 54 Sex: M Citation Issued: N

Direction of Travel: NORTH-WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH Driveway

6/16/2015 Tue 06:45 AM Persons Killed: 0 Persons Injured: 1 Extent of Injuries: C **Case: 2015-35764757**

Accident Class: INJURY Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLLISION WITH DEER Traffic Control: NONE
Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DAWN
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3228 State of Registration: NY

Num of Occupants: 1 Driver's Age: 21 Sex: M Citation Issued: N

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
117 Meters North of Marble Rd

6/15/2015 Mon 16:00 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35764768**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE
Manner of Collision: REAR END Weather: CLEAR
Road Surface Condition: DRY Road Char.: CURVE AND GRADE Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3342 State of Registration: NY

Num of Occupants: 2 Driver's Age: 33 Sex: M Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: NOT APPLICABLE, FAILURE TO YIELD RIGHT OF WAY

Veh :2 CAR/VAN/PICKUP Registered Weight: 3458 State of Registration: NY

Num of Occupants: 1 Driver's Age: 57 Sex: M Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
402 Meters North of [Route] 37

6/10/2015 Wed 21:16 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35766091**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 25 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031091 Street: STATE HIGHWAY 8

6/19/2015 Fri 08:25 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35775250**

Accident Class: PROPERTY DAMAGE | Police Agency: SP GREENE SATELLITE | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2621 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 22 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35
6 Meters West of Driveway

6/24/2015 Wed 19:49 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35789782**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 2 Driver's Age: 64 Sex: M Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

7/19/2015 Sun 14:21 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: B | **Case: 2015-35807882**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 MOTORCYCLE Registered Weight: 788 State of Registration: NY

Num of Occupants: 1 Driver's Age: 62 Sex: M Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

7/24/2015 Fri 21:15 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35815741**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 42 Sex: F Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

8/5/2015 Wed 00:10 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35836168**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NONE

Manner of Collision: OTHER | Weather: FOG/SMOG/SMOKE

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 21 | Sex: M | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: AVOIDING OBJECT IN ROADWAY

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
110 Meters North of E Guilford Rd

8/21/2015 Fri 13:01 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35856037**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: OTHER NON-COLLISION | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 TRUCK | Registered Weight: | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 45 | Sex: M | Citation Issued: Y

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: OVERSIZED VEHICLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031042 Street: STATE HIGHWAY 8
87 Meters North of County Rte 40

8/10/2015 Mon 09:41 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35857506**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: OVERTAKING | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 2 Driver's Age: Sex: Citation Issued:
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: PARKED
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 TRUCK Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 58 Sex: M Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, OTHER (VEHICLE)

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
62 Meters North of Robinson Rd

8/9/2015 Sun 07:13 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35859074**
Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 21 Sex: M Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031010 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Davis Ln

8/24/2015 Mon 17:20 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35867681**
Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE
Manner of Collision: REAR END | Weather: CLEAR

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 44 | Sex: M | Citation Issued: N
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 26 | Sex: F | Citation Issued: Y
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: UNSAFE SPEED, FOLLOWING TOO CLOSELY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031081 Street: [Route] 8
15 Meters North of [Route] 37

8/16/2015 Sun 06:56 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35888228**
Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 3
Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: FOG/SMOG/SMOKE
Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAWN
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 9200 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 21 | Sex: M | Citation Issued: Y
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: UNSAFE LANE CHANGE, DRIVER INATTENTION

Veh :3 CAR/VAN/PICKUP | Registered Weight: 4271 | State of Registration: NY
Num of Occupants: 2 | Driver's Age: | Sex: | Citation Issued:
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: PARKED
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 3208 | State of Registration: NY

Num of Occupants: 2 Driver's Age: Sex: Citation Issued:

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: PARKED

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
161 Meters North of Robinson Rd

9/18/2015 Fri 10:03 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35892661**

Accident Class: NON-REPORTABLE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 3 Driver's Age: 20 Sex: M Citation Issued: Y

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE LANE CHANGE, DRIVER INATTENTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH County Road 36

9/20/2015 Sun 01:30 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35894250**

Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL Traffic Control: STOP SIGN

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD LIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2405 State of Registration: NY

Num of Occupants: 1 Driver's Age: 20 Sex: M Citation Issued: Y

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: TRAFFIC CONTROL DEVICES DISREGARDED, ALCOHOL INVOLVEMENT

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
AT INTERSECTION WITH N Pond Rd

9/18/2015 Fri 17:09 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2015-35897490**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: SP GREENE SATELLITE | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: STOP SIGN

Manner of Collision: RIGHT ANGLE | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 1698 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 74 | Sex: M | Citation Issued: Y

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, NOT APPLICABLE

Veh :1 MOTORCYCLE | Registered Weight: 304 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 18 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
220 Meters West of E Guilford Rd

9/21/2015 Mon 08:42 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2015-35900518**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 TRUCK | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 77 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE LANE CHANGE, LOST CONSCIOUSNESS

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031082 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Church St

9/22/2015 Tue 20:45 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35906205**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: REAR END | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD LIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 2 | Driver's Age: | Sex: | Citation Issued:

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: PARKED

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: FL

Num of Occupants: 1 | Driver's Age: 21 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: BACKING

Apparent Factors: BACKING UNSAFELY, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031089 Street: STATE HIGHWAY 8

9/21/2015 Mon 11:32 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35906614**

Accident Class: NON-REPORTABLE | Police Agency: NORWICH SP | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NONE

Manner of Collision: SIDESWIPE | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 TRUCK | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 46 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 TRUCK | Registered Weight: | State of Registration: IN

Num of Occupants: 1 | Driver's Age: 48 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO KEEP RIGHT, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031019 Street: STATE HIGHWAY 8
438 Meters South of Unnamed Street

10/6/2015 Tue 03:04 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35919128**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NB

Num of Occupants: 2 | Driver's Age: 24 | Sex: F | Citation Issued: Y

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: CELL PHONE (HAND HELD), DRIVER INATTENTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

10/13/2015 Tue 06:30 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35926979**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAWN

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 7600 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 58 | Sex: M | Citation Issued: N

Direction of Travel: NORTH-WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH Ives Settlement Rd

10/23/2015 Fri 12:39 PM | Persons Killed: 0 | Persons Injured: 2 | Extent of Injuries: BB | **Case: 2015-35946086**

Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NYSP SIDNEY Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE
Manner of Collision: LEFT TURN (AGAINST OTHER CAR) Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 3606 State of Registration: NY
Num of Occupants: 1 Driver's Age: 71 Sex: M Citation Issued: N
Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2769 State of Registration: NY
Num of Occupants: 1 Driver's Age: 69 Sex: F Citation Issued: Y
Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: MAKING LEFT TURN
Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031058 Street: STATE HIGHWAY 8
62 Meters South of Driveway

11/1/2015 Sun 17:30 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35949102**
Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLLISION WITH DEER Traffic Control: NONE
Manner of Collision: OTHER Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3010 State of Registration: NY
Num of Occupants: 1 Driver's Age: 59 Sex: F Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35

10/17/2015 Sat 12:30 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35949952**
Accident Class: PROPERTY DAMAGE Police Agency: Num of Veh: 1
Type Of Accident: COLLISION WITH DEER Traffic Control: NONE
Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2950 State of Registration: NY

Num of Occupants: 1 Driver's Age: 20 Sex: F Citation Issued: N

Direction of Travel: NORTH-WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT ENTERED, NOT ENTERED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031021 Street: STATE HIGHWAY 8
184 Meters South of Unnamed Street

11/4/2015 Wed 09:30 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35956644**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 65 Sex: U Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031076 Street: STATE HIGHWAY 8
200 Meters North of Easyliving Trailer Park

11/4/2015 Wed 04:45 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35956648**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 2 Driver's Age: 23 Sex: F Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031044 Street: STATE HIGHWAY 8
60 Meters South of Hitching Post Ln

11/12/2015 Thu 11:38 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2015-35965018**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE

Manner of Collision: REAR END Weather: CLOUDY

Road Surface Condition: WET | Road Char.: CURVE AND GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 3995 State of Registration: NY

Num of Occupants: 1 Driver's Age: 20 Sex: F Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3086 State of Registration: NY

Num of Occupants: 1 Driver's Age: 42 Sex: M Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, FOLLOWING TOO CLOSELY

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031002 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Kelly Rd

11/10/2015 Tue 14:45 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2015-35965123**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE

Manner of Collision: REAR END Weather: RAIN

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3700 State of Registration: NY

Num of Occupants: 1 Driver's Age: 64 Sex: F Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 3378 State of Registration: NY

Num of Occupants: 1 Driver's Age: 17 Sex: F Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, FOLLOWING TOO CLOSELY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031044 Street: STATE HIGHWAY 8
23 Meters North of Hitching Post Ln

11/12/2015 Thu 06:03 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35966213**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 9200 State of Registration: NY

Num of Occupants: 2 Driver's Age: 49 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, FAILURE TO YIELD RIGHT OF WAY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

11/13/2015 Fri 17:25 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35966216**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: RAIN

Road Surface Condition: WET Road Char.: STRAIGHT/ GRADE Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 48 Sex: F Citation Issued: N

Direction of Travel: NORTH-WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031081 Street: STATE HIGHWAY 8
12 Meters North of State Highway 51

10/30/2015 Fri 16:48 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35967680**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: LEFT TURN (AGAINST OTHER CAR) | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 32 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: | State of Registration: PA

Num of Occupants: 1 | Driver's Age: 43 | Sex: M | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PASSING OR LANE USAGE IMPROPERLY, NOT APPLICABLE

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031003 Street: STATE HIGHWAY 8
129 Meters North of Unnamed Street

11/14/2015 Sat 17:40 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-35971074**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NONE

Manner of Collision: RIGHT ANGLE | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD LIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 70 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: BACKING

Apparent Factors: BACKING UNSAFELY, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 2 Driver's Age: Sex: Citation Issued:

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: PARKED

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031103 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Shumway Rd

11/21/2015 Sat 11:50 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35977063**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: OTHER

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2965 State of Registration: NY

Num of Occupants: 1 Driver's Age: 44 Sex: F Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
88 Meters West of Gonzer Rd

10/29/2015 Thu 23:49 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-35997628**

Accident Class: NON-REPORTABLE Police Agency: NYSP ONEONTA Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT/ GRADE Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 OTHER Registered Weight: State of Registration: NY

Num of Occupants: 2 Driver's Age: 29 Sex: M Citation Issued: N

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street:

11/24/2015 Tue 17:05 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-36006606**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2756 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 49 | Sex: F | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
180 Meters East of Unnamed Street

12/16/2015 Wed 17:23 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-36014970**

Accident Class: PROPERTY DAMAGE | Police Agency: SP GREENE SATELLITE | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 4365 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 34 | Sex: F | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031076 Street: [Route] 8
151 Meters North of Easyliving Trailer Park

12/16/2015 Wed 18:40 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-36049308**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 59 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031048 Street: STATE HIGHWAY 8
470 Meters North of Hitching Post Ln

1/15/2016 Fri 22:52 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36053763**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 4022 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 25 | Sex: F | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031009 Street: STATE HIGHWAY 8
116 Meters South of Davis Ln

1/13/2016 Wed 13:17 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36053793**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 3

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 5005 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 23 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: FOLLOWING TOO CLOSELY, NOT APPLICABLE

Veh :1 TRUCK Registered Weight: State of Registration: PA

Num of Occupants: 1 Driver's Age: 59 Sex: M Citation Issued: Y

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, FOLLOWING TOO CLOSELY

Veh :3 CAR/VAN/PICKUP Registered Weight: 2945 State of Registration: NY

Num of Occupants: 1 Driver's Age: 68 Sex: F Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
30 Meters North of County Road 35

1/12/2016 Tue 14:56 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36053795**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH SIGN POST Traffic Control: NONE

Manner of Collision: OTHER Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 68 Sex: M Citation Issued: N

Direction of Travel: NORTH-WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: MAKING RIGHT TURN

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
161 Meters South of WAHLBERG RD

12/31/2015 Thu 23:38 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2015-36060557**

Accident Class: NON-REPORTABLE Police Agency: CHENANGO CO SO Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NONE

Manner of Collision: OTHER Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 17 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
340 Meters North of N Pond Rd

1/20/2016 Wed 07:48 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36061839**

Accident Class: NON-REPORTABLE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 18 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
161 Meters South of WAHLBERG RD

12/31/2015 Thu 23:38 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-36065443**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 22 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031004 Street: STATE HIGHWAY 8
139 Meters North of Unnamed Street

11/12/2015 Thu 18:00 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2015-36067598**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: RAIN

Road Surface Condition: WET | Road Char.: CURVE AND GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 22 | Sex: F | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
655 Meters North of N Pond Rd

1/24/2016 Sun 04:20 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2016-36069218**

Accident Class: INJURY | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2976 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 22 | Sex: F | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO KEEP RIGHT, FELL ASLEEP

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35
259 Meters West of E Guilford Rd

1/22/2016 Fri 06:30 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36071759**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER
Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER
Weather: CLEAR
Road Surface Condition: DRY
Road Char.: STRAIGHT AND LEVEL
Light Condition: DAWN
Loc. of Ped/Bicycle: NOT APPLICABLE
Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 35 Sex: M Citation Issued: N
Direction of Travel: EAST
Public Property Damage: OTHER
School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH County Road 36

1/29/2016 Fri 10:43 AM Persons Killed: 0 Persons Injured: 2 Extent of Injuries: CC **Case: 2016-36077512**
Accident Class: PROPERTY DAMAGE AND INJURY
Police Agency: NYSP SIDNEY
Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE
Traffic Control: YIELD SIGN
Manner of Collision: RIGHT ANGLE
Weather: CLOUDY
Road Surface Condition: WET
Road Char.: STRAIGHT AND LEVEL
Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE
Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3058 State of Registration: NY
Num of Occupants: 1 Driver's Age: 18 Sex: F Citation Issued: N
Direction of Travel: WEST
Public Property Damage: OTHER
School Bus Involved: OTHER
Pre-Accd Action: MAKING RIGHT TURN
Apparent Factors: NOT APPLICABLE, UNSAFE SPEED

Veh :2 CAR/VAN/PICKUP Registered Weight: 4200 State of Registration: NY
Num of Occupants: 3 Driver's Age: 59 Sex: F Citation Issued: N
Direction of Travel: SOUTH
Public Property Damage: OTHER
School Bus Involved: OTHER
Pre-Accd Action: MAKING LEFT TURN
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031081 Street: [Route] 37
AT INTERSECTION WITH [Route] 8

2/23/2016 Tue 08:00 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36120139**
Accident Class: PROPERTY DAMAGE
Police Agency:
Num of Veh: 1
Type Of Accident: COLLISION WITH DEER
Traffic Control: NONE

Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: DRY Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE
Veh :1 CAR/VAN/PICKUP Registered Weight: 3846 State of Registration: NY
Num of Occupants: 1 Driver's Age: 53 Sex: F Citation Issued: N
Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT ENTERED, NOT ENTERED
County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031006 Street: STATE HIGHWAY 8
93 Meters South of Driveway

4/3/2016 Sun 07:01 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36162507**
Accident Class: NON-REPORTABLE Police Agency: RICHFIELD SPRINGS SP Num of Veh: 1
Type Of Accident: COLLISION WITH GUIDE RAIL Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: SNOW/ICE Road Char.: CURVE AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE
Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 21 Sex: M Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED
County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031007 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Driveway

4/3/2016 Sun 07:05 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36162510**
Accident Class: PROPERTY DAMAGE Police Agency: RICHFIELD SPRINGS SP Num of Veh: 1
Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: SNOW/ICE Road Char.: CURVE AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE
Veh :1 CAR/VAN/PICKUP Registered Weight: 3410 State of Registration: NY
Num of Occupants: 1 Driver's Age: 24 Sex: F Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031013 Street: STATE HIGHWAY 8
356 Meters North of Old County Road 43

4/3/2016 Sun 07:35 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36167267**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: MD

Num of Occupants: 1 | Driver's Age: 21 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 37
14 Meters East of Driveway

2/21/2016 Sun 19:09 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36170376**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH TREE | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 43 | Sex: F | Citation Issued: Y

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNKNOWN, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031010 Street: STATE HIGHWAY 8
71 Meters North of Davis Ln

4/9/2016 Sat 12:47 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36171576**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH SIGN POST | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 20 | Sex: F | Citation Issued: Y
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: UNSAFE LANE CHANGE, FATIGUED/DROWSY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
15 Meters South of JOSLYN RD

4/2/2016 Sat 11:20 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: B | **Case: 2016-36186428**
Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: CHENANGO CO SO | Num of Veh: 1
Type Of Accident: OVERTURNED | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: CT
Num of Occupants: 1 | Driver's Age: 20 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: REACTION TO OTHER UNINVOLVED VEHICL, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031050 Street: STATE HIGHWAY 8

4/24/2016 Sun 20:18 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36186619**
Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3355 State of Registration: NY
Num of Occupants: 1 Driver's Age: 62 Sex: F Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
365 Meters North of Robinson Stub Rd

4/23/2016 Sat 00:23 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36186620**
Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLLISION WITH DEER Traffic Control: NONE
Manner of Collision: OTHER Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 5208 State of Registration: NY
Num of Occupants: 2 Driver's Age: 50 Sex: M Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031033 Street: STATE HIGHWAY 8
152 Meters North of Old State Highway 8 S

5/6/2016 Fri 14:53 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36198105**
Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE
Manner of Collision: OVERTAKING Weather: CLOUDY
Road Surface Condition: WET Road Char.: CURVE AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: VA
Num of Occupants: 1 Driver's Age: 69 Sex: M Citation Issued: Y
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: OVERTAKING
Apparent Factors: UNSAFE LANE CHANGE, PASSING TOO CLOSELY

Veh :2 TRUCK Registered Weight: 117000 State of Registration: NY
Num of Occupants: 1 Driver's Age: 61 Sex: M Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
347 Meters South of Allen Rd

5/9/2016 Mon 06:18 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36202323**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 41 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35
84 Meters South of Robinson Rd

5/20/2016 Fri 05:50 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36241734**

Accident Class: PROPERTY DAMAGE | Police Agency: | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: UNKNOWN

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 4387 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 58 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT ENTERED, NOT ENTERED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
852 Meters South of Parker Rd

6/14/2016 Tue 21:12 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36257932**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH ANIMAL | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 4 | Driver's Age: 45 | Sex: M | Citation Issued: N
Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031044 Street: STATE HIGHWAY 8
28 Meters North of Hitching Post Ln

6/2/2016 Thu 23:35 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36262679**
Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH TREE | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 3 | Driver's Age: 30 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, OBSTRUCTION/DEBRIS

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

6/1/2016 Wed 12:08 PM | Persons Killed: 0 | Persons Injured: 2 | Extent of Injuries: AC | **Case: 2016-36263402**
Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: CHENANGO CO SO | Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE
Manner of Collision: HEAD ON | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 3380 | State of Registration: NY

Num of Occupants: 1 Driver's Age: 56 Sex: M Citation Issued: N

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, OTHER (VEHICLE)

Veh :1 CAR/VAN/PICKUP Registered Weight: 3158 State of Registration: NY

Num of Occupants: 1 Driver's Age: 21 Sex: F Citation Issued: Y

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: DRIVER INATTENTION, UNSAFE LANE CHANGE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031081 Street: STATE HIGHWAY 8
AT INTERSECTION WITH State Highway 51

7/2/2016 Sat 08:38 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36282048**

Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLLISION WITH OTHER FIXED OBJECT Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: MA

Num of Occupants: 4 Driver's Age: 43 Sex: F Citation Issued: Y

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE LANE CHANGE, FELL ASLEEP

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH Robinson Stub Rd

6/30/2016 Thu 21:20 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36287277**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3569 State of Registration: NY

Num of Occupants: 1 Driver's Age: 66 Sex: F Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031013 Street: [Route] 8
368 Meters North of Old County Road 43

6/26/2016 Sun 12:00 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36296827**

Accident Class: PROPERTY DAMAGE | Police Agency: | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 OTHER | Registered Weight: | State of Registration: NJ

Num of Occupants: 2 | Driver's Age: 51 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT ENTERED, NOT ENTERED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
905 Meters South of N Pond Rd

8/28/2016 Sun 12:32 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36361705**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1
Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2435 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 19 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE LANE CHANGE, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
217 Meters West of Phillip Odell Rd

8/28/2016 Sun 20:15 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36366579**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3186 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 26 | Sex: F | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35
5 Meters North of Driveway

8/7/2016 Sun 07:00 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36383796**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH OTHER FIXED OBJECT | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 OTHER | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: | Sex: U | Citation Issued: N

Direction of Travel: UNKNOWN | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, UNKNOWN

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031051 Street: [Route] 8

9/10/2016 Sat 14:00 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36391379**

Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH TREE | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3300 State of Registration: NY

Num of Occupants: 1 Driver's Age: 76 Sex: M Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: TIRE FAILURE/INADEQUATE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
409 Meters North of Joslyn Rd

9/21/2016 Wed 10:50 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36395766**

Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: HIGHWAY WORK AREA

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2773 State of Registration: NY

Num of Occupants: 1 Driver's Age: 20 Sex: M Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: FELL ASLEEP, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

10/1/2016 Sat 23:00 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36414468**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: RAIN

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 21 Sex: M Citation Issued: N

Direction of Travel: SOUTH-EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031015 Street: STATE HIGHWAY 8
AT INTERSECTION WITH County Road 35

10/3/2016 Mon 15:52 PM | Persons Killed: 0 | Persons Injured: 3 | Extent of Injuries: CCC | **Case: 2016-36420799**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: REAR END | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 8200 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 63 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 3709 | State of Registration: NY

Num of Occupants: 4 | Driver's Age: 54 | Sex: M | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, PASSING OR LANE USAGE IMPROPERLY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031096 Street: STATE HIGHWAY 8
125 Meters South of Crandall Rd

10/11/2016 Tue 04:35 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2016-36423921**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: HEAD ON | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3141 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 83 | Sex: F | Citation Issued: Y

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: NOT APPLICABLE, FAILURE TO YIELD RIGHT OF WAY

Veh :2 CAR/VAN/PICKUP Registered Weight: 3111 State of Registration: NY

Num of Occupants: 1 Driver's Age: 49 Sex: F Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
66 Meters North of Marble Rd

10/21/2016 Fri 08:04 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36434425**

Accident Class: PROPERTY DAMAGE Police Agency: SP GREENE SATELLITE Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: WET Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2745 State of Registration: NY

Num of Occupants: 1 Driver's Age: 27 Sex: F Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031015 Street: STATE HIGHWAY 8
AT INTERSECTION WITH County Road 35

10/8/2016 Sat 17:45 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36437028**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NO PASSING ZONE

Manner of Collision: LEFT TURN (AGAINST OTHER CAR) Weather: CLOUDY

Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DUSK

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3260 State of Registration: NY

Num of Occupants: 2 Driver's Age: 57 Sex: F Citation Issued: N

Direction of Travel: NORTH-WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: NOT APPLICABLE, FAILURE TO YIELD RIGHT OF WAY

Veh :2 CAR/VAN/PICKUP Registered Weight: 3361 State of Registration: NY

Num of Occupants: 1 Driver's Age: 24 Sex: M Citation Issued: Y

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031046 Street: STATE HIGHWAY 8
155 Meters North of Hitching Post Ln

10/23/2016 Sun 18:16 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36443716**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 22 Sex: F Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

10/25/2016 Tue 18:22 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36443720**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: DRY Road Char.: STRAIGHT/ GRADE Light Condition: DUSK

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3107 State of Registration: NY

Num of Occupants: 1 Driver's Age: 67 Sex: M Citation Issued: N

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
312 Meters West of Phillip Odell Rd

11/10/2016 Thu 07:20 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36467246**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3162 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 40 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35
AT INTERSECTION WITH PHILLIP ODELL RD

11/16/2016 Wed 05:57 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36483043**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: FOG/SMOG/SMOKE

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 TRUCK | Registered Weight: | State of Registration: NY

Num of Occupants: 3 | Driver's Age: 28 | Sex: M | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031005 Street: STATE HIGHWAY 8
258 Meters South of Driveway

11/20/2016 Sun 04:25 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36485606**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH TREE | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: SNOW
Road Surface Condition: SLUSH Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4801 State of Registration: NY
Num of Occupants: 1 Driver's Age: 72 Sex: M Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: OBSTRUCTION/DEBRIS, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031044 Street: [Route] 8
19 Meters South of Hitching Post Ln

11/19/2016 Sat 06:55 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36485631**
Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER Weather: FOG/SMOG/SMOKE
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2740 State of Registration: NY
Num of Occupants: 1 Driver's Age: 25 Sex: M Citation Issued: N
Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031011 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Old County Road 43

11/21/2016 Mon 09:15 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36485663**
Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLL. W/EARTH CUT/DITCH ELE./ROCK Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER Weather: SNOW
Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 5121 State of Registration: NY
Num of Occupants: 1 Driver's Age: 70 Sex: F Citation Issued: Y

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031040 Street: STATE HIGHWAY 8
229 Meters South of Rockdale Rd

10/28/2016 Fri 23:17 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36527732**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 3

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :3 CAR/VAN/PICKUP | Registered Weight: 4449 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: | Sex: | Citation Issued:

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: PARKED

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 4500 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: | Sex: | Citation Issued:

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: PARKED

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 5723 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 24 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, DRUGS (ILLEGAL)

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031081 Street: STATE HIGHWAY 8
29 Meters North of Unnamed Street

12/16/2016 Fri 16:06 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36527752**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 3

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3181 State of Registration: NY
Num of Occupants: 1 Driver's Age: 61 Sex: F Citation Issued: Y
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: PAVEMENT SLIPPERY, REACTION TO OTHER UNINVOLVED VEHICL

Veh :2 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: Sex: Citation Issued:
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: PARKED
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :3 CAR/VAN/PICKUP Registered Weight: 3421 State of Registration: NY
Num of Occupants: 1 Driver's Age: Sex: Citation Issued:
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: PARKED
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

11/17/2016 Thu 17:58 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2016-36527753**
Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLLISION WITH ANIMAL Traffic Control: NONE
Manner of Collision: OTHER Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 58 Sex: M Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
97 Meters West of Phillip Odell Rd

12/13/2016 Tue 07:03 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36527765**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2547 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 43 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
958 Meters South of Parker Rd

11/11/2016 Fri 17:09 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-36535091**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DUSK

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 68 | Sex: M | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
291 Meters East of Gonzer Rd

1/6/2017 Fri 06:02 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36553783**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT/ GRADE Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 5562 State of Registration: NY
Num of Occupants: 1 Driver's Age: 42 Sex: M Citation Issued: N
Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031043 Street: [Route] 8
89 Meters South of Hitching Post Ln

1/6/2017 Fri 19:00 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36556895**
Accident Class: NON-REPORTABLE Police Agency: CHENANGO CO SO Num of Veh: 1
Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 45 Sex: M Citation Issued: N
Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
276 Meters West of E Guilford Rd

1/8/2017 Sun 22:35 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36563670**
Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NONE
Manner of Collision: OTHER Weather: SNOW
Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT/ GRADE Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 26 Sex: M Citation Issued: N

Direction of Travel: NORTH-WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031020 Street: STATE HIGHWAY 8
310 Meters South of Unnamed Street

1/4/2017 Wed 10:00 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36564359**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH OTHER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 44 | Sex: F | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, OBSTRUCTION/DEBRIS

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031048 Street: STATE HIGHWAY 8
425 Meters North of Hitching Post Ln

1/9/2017 Mon 19:24 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36564388**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3273 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 35 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031090 Street: STATE HIGHWAY 8

1/16/2017 Mon 16:40 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36570370**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 5255 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 65 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031038 Street: STATE HIGHWAY 8
472 Meters South of Rockdale Rd

1/17/2017 Tue 05:36 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36572101**
Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 52 | Sex: F | Citation Issued: N
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031015 Street: STATE HIGHWAY 8
AT INTERSECTION WITH County Road 35

1/13/2017 Fri 08:47 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36572106**
Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: STOP SIGN
Manner of Collision: RIGHT ANGLE | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 75 | Sex: F | Citation Issued: Y

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 54 | Sex: F | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, REACTION TO OTHER UNINVOLVED VEHICL

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031006 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Driveway

1/14/2017 Sat 02:49 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36572112**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDERAIL - END | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3390 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 32 | Sex: M | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE LANE CHANGE, ALCOHOL INVOLVEMENT

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH State Highway 8

1/18/2017 Wed 17:05 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36572878**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: OTHER NON-COLLISION | Traffic Control: FLASHING LIGHT

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 48 | Sex: F | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: STOPPED IN TRAFFIC

Apparent Factors: OBSTRUCTION/DEBRIS, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031038 Street: STATE HIGHWAY 8
482 Meters South of Rockdale Rd

1/27/2017 | Fri 07:26 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36582909**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAWN

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 24 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031049 Street: STATE HIGHWAY 8
566 Meters North of Hitching Post Ln

2/1/2017 | Wed 19:03 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36597049**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP ONEONTA | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 OTHER | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 24 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
76 Meters North of E GUILFORD RD

1/31/2017 Tue 12:00 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36628105**

Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NONE

Manner of Collision: RIGHT TURN (WITH OTHER CAR) | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: CURVE AND GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 5900 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 53 | Sex: M | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING RIGHT TURN

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 3460 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 29 | Sex: M | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, PASSING OR LANE USAGE IMPROPERLY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031026 Street: STATE HIGHWAY 8

1/30/2017 Mon 22:24 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36636590**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH OTHER FIXED OBJECT | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 37 | Sex: M | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO KEEP RIGHT, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
387 Meters South of Robinson Stub Rd

3/8/2017 Wed 00:18 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36639756**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 58 Sex: M Citation Issued: N

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031049 Street: STATE HIGHWAY 8

3/14/2017 Tue 15:08 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36645178**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE

Manner of Collision: SIDESWIPE Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 9500 State of Registration: NY

Num of Occupants: 1 Driver's Age: 31 Sex: M Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

Veh :2 CAR/VAN/PICKUP Registered Weight: 6900 State of Registration: NY

Num of Occupants: 1 Driver's Age: 58 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
57 Meters East of County Road 36

3/18/2017 Sat 17:25 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36649434**

Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: CURVE AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2756 State of Registration: NY

Num of Occupants: 2 Driver's Age: 20 Sex: F Citation Issued: N

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031002 Street: STATE HIGHWAY 8
33 Meters South of Unnamed Street

4/7/2017 Fri 12:24 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36685648**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NO PASSING ZONE

Manner of Collision: REAR END Weather: RAIN

Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 5278 State of Registration: NY

Num of Occupants: 1 Driver's Age: 24 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FOLLOWING TOO CLOSELY, UNSAFE SPEED

Veh :2 TRUCK Registered Weight: 107000 State of Registration: NY

Num of Occupants: 1 Driver's Age: 56 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: STOPPED IN TRAFFIC

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031005 Street: STATE HIGHWAY 8
274 Meters South of Driveway

5/5/2017 Fri 07:04 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2017-36713105**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: REAR END | Weather: RAIN

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3945 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 94 | Sex: M | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: FOLLOWING TOO CLOSELY, PAVEMENT SLIPPERY

Veh :2 CAR/VAN/PICKUP | Registered Weight: 3060 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 46 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: STOPPED IN TRAFFIC

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031024 Street: STATE HIGHWAY 8
320 Meters North of Unnamed Street

5/9/2017 Tue 23:27 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36721223**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2587 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 34 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO KEEP RIGHT, TIRE FAILURE/INADEQUATE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

5/23/2017 Tue 12:06 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36738970**

Accident Class: PROPERTY DAMAGE | Police Agency: SP GREENE SATELLITE | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3311 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 64 | Sex: F | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
763 Meters South of Parker Rd

6/8/2017 Thu 17:29 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36757197**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 28 | Sex: F | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031063 Street: STATE HIGHWAY 8
168 Meters West of Hazy Ridge Ln

6/2/2017 Fri 21:57 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36757198**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: OVERTURNED | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 MOTORCYCLE Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 20 Sex: M Citation Issued: Y
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: UNSAFE SPEED, PASSING OR LANE USAGE IMPROPERLY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031015 Street: STATE HIGHWAY 8 AT INTERSECTION WITH County Road 35

6/22/2017 Thu 12:17 PM Persons Killed: 0 Persons Injured: 2 Extent of Injuries: BC **Case: 2017-36779833**
Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NYSP SIDNEY Num of Veh: 3
Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: TRAFFIC SIGNAL
Manner of Collision: OTHER Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 3125 State of Registration: NY
Num of Occupants: 1 Driver's Age: 80 Sex: F Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: STOPPED IN TRAFFIC
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3488 State of Registration: NY
Num of Occupants: 1 Driver's Age: 81 Sex: F Citation Issued: Y
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: FOLLOWING TOO CLOSELY, UNSAFE SPEED

Veh :3 CAR/VAN/PICKUP Registered Weight: 4295 State of Registration: NY
Num of Occupants: 1 Driver's Age: 58 Sex: M Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: STOPPED IN TRAFFIC

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 37
152 Meters West of PHILLIP ODELL RD

6/17/2017 Sat 05:15 AM | Persons Killed: 0 | Persons Injured: 2 | Extent of Injuries: BC | **Case: 2017-36781059**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAWN

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3391 | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 26 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: WHITES HILL RD
402 Meters West of BLOWER RD

6/13/2017 Tue 18:51 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36781073**

Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH ANIMAL | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 8500 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 44 | Sex: M | Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
1510 Meters West of Mount Upton St

6/25/2017 Sun 21:52 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36781385**

Accident Class: NON-REPORTABLE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 28 | Sex: M | Citation Issued: N
Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
AT INTERSECTION WITH Whites Hill Rd

7/11/2017 Tue 16:06 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2017-36808158**
Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NORWICH SP | Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: STOP SIGN
Manner of Collision: RIGHT ANGLE | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3237 | State of Registration: NY
Num of Occupants: 2 | Driver's Age: 32 | Sex: F | Citation Issued: Y
Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: TRAFFIC CONTROL DEVICES DISREGARDED, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP | Registered Weight: 2432 | State of Registration: NY
Num of Occupants: 2 | Driver's Age: 18 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35
30 Meters East of MARBLE RD

7/12/2017 Wed 11:28 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36810651**
Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: RAIN
Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE
Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: PA
Num of Occupants: 1 Driver's Age: 67 Sex: M Citation Issued: N
Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION
County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031071 Street: STATE HIGHWAY 8
1122 Meters North of Hazy Ridge Ln

8/4/2017 Fri 13:40 PM Persons Killed: 0 Persons Injured: 1 Extent of Injuries: B **Case: 2017-36835747**
Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NONE
Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE
Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: PA
Num of Occupants: 1 Driver's Age: 20 Sex: F Citation Issued: N
Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: UNSAFE LANE CHANGE, FELL ASLEEP
County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031031 Street: STATE HIGHWAY 8
67 Meters South of Old State Highway 8 S

8/8/2017 Tue 11:15 AM Persons Killed: 0 Persons Injured: 1 Extent of Injuries: C **Case: 2017-36843145**
Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NYSP SIDNEY Num of Veh: 1
Type Of Accident: COLLISION WITH TREE Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER Weather: CLEAR
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE
Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY
Num of Occupants: 1 Driver's Age: 36 Sex: F Citation Issued: Y

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: DRIVER INATTENTION, UNSAFE LANE CHANGE

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031003 Street: STATE HIGHWAY 8
47 Meters North of Unnamed Street

8/7/2017 Mon 12:30 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36846102**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH CUT/DITCH | ELE./ROCK | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: RAIN

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 2 | Driver's Age: 61 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: TIRE FAILURE/INADEQUATE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

9/7/2017 Thu 19:00 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36886863**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: RAIN

Road Surface Condition: WET | Road Char.: CURVE AND GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 78 | Sex: M | Citation Issued: N

Direction of Travel: NORTH-WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
76 Meters North of N POND RD

8/29/2017 Tue 00:16 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2017-36888980**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: CHENANGO CO SO | Num of Veh: 1
Type Of Accident: COLLISION WITH ANIMAL | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: CURVE AND GRADE | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 6800 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 57 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35
AT INTERSECTION WITH IVES SETTLEMENT RD

8/30/2017 Wed 00:00 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36892220**
Accident Class: PROPERTY DAMAGE | Police Agency: | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: TRAFFIC SIGNAL
Manner of Collision: OTHER | Weather: FOG/SMOG/SMOKE
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAWN
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 5800 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 50 | Sex: F | Citation Issued: N
Direction of Travel: SOUTH-EAST | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT ENTERED, NOT ENTERED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031083 Street: STATE HIGHWAY 8
141 Meters North of Mill St

9/22/2017 Fri 19:12 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36903964**
Accident Class: NON-REPORTABLE | Police Agency: NORWICH SP | Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE
Manner of Collision: REAR END | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD LIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY

Num of Occupants: 1 Driver's Age: 45 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 24 Sex: M Citation Issued: Y

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, FOLLOWING TOO CLOSELY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031009 Street: STATE HIGHWAY 8
64 Meters South of Davis Ln

10/25/2017 Wed 18:17 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36955986**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 6939 State of Registration: NY

Num of Occupants: 1 Driver's Age: 52 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031094 Street: STATE HIGHWAY 8
402 Meters South of CRANDALL RD

11/5/2017 Sun 05:06 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36967035**

Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: WET Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3989 State of Registration: NY

Num of Occupants: 2 Driver's Age: 71 Sex: M Citation Issued: N

Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35

10/31/2017 Tue 06:49 AM Persons Killed: 0 Persons Injured: 1 Extent of Injuries: C **Case: 2017-36967690**

Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: CHENANGO CO SO Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DAWN

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4438 State of Registration: NY

Num of Occupants: 1 Driver's Age: 60 Sex: F Citation Issued: N

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: WHITES HILL RD
175 Meters West of Darlin Ln

11/7/2017 Tue 05:47 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36968895**

Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4588 State of Registration: NY

Num of Occupants: 1 Driver's Age: 35 Sex: F Citation Issued: N

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
323 Meters South of Driveway

11/8/2017 Wed 17:04 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36974256**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3490 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 67 | Sex: F | Citation Issued: N
Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 35

10/31/2017 Tue 06:49 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36981963**
Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAWN
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3389 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 49 | Sex: F | Citation Issued: N
Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
652 Meters West of Mount Upton St

11/9/2017 Thu 16:11 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-36990439**
Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1
Type Of Accident: COLL. W/LIGHT SUPPORT/UTILITY POLE | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: CURVE AND GRADE | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3816 | State of Registration: NY

Num of Occupants: 1 Driver's Age: 39 Sex: F Citation Issued: Y

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, UNSAFE LANE CHANGE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031103 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Shumway Rd

11/10/2017 Fri 07:58 AM Persons Killed: 0 Persons Injured: 2 Extent of Injuries: BC **Case: 2017-36998069**

Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NYSP SIDNEY Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: YIELD SIGN

Manner of Collision: HEAD ON Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 3257 State of Registration: NY

Num of Occupants: 1 Driver's Age: 57 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3840 State of Registration: NY

Num of Occupants: 1 Driver's Age: 28 Sex: F Citation Issued: Y

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
698 Meters North of Robinson Stub Rd

11/11/2017 Sat 06:16 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2017-36998070**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH DEER Traffic Control: NONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: DRY Road Char.: STRAIGHT/ GRADE Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4666 State of Registration: NY

Num of Occupants: 1 Driver's Age: 29 Sex: M Citation Issued: N

Direction of Travel: NORTH-WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031053 Street: STATE HIGHWAY 8
44 Meters South of Medburry Rd

11/29/2017 Wed 06:25 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37009747**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3064 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 32 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031035 Street: STATE HIGHWAY 8
454 Meters North of Old State Highway 8 S

11/29/2017 Wed 23:40 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37020876**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3296 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 62 | Sex: F | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031104 Street: STATE HIGHWAY 8
272 Meters North of Shumway Rd

12/12/2017 Tue 03:40 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37031192**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 9800 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 36 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031040 Street: [Route] 8
152 Meters South of ROCKDALE RD

12/10/2017 Sun 22:52 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37035121**
Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 54 | Sex: F | Citation Issued: N
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: MILLER RD
83 Meters North of Whites Hill Rd

12/19/2017 Tue 06:58 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37050844**
Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: WET | Road Char.: STRAIGHT AT HILLCREST | Light Condition: DAWN

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 14000 State of Registration: NY

Num of Occupants: 1 Driver's Age: 27 Sex: M Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031011 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Old County Road 43

12/17/2017 Sun 17:55 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37050853**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 55 Sex: F Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36

12/26/2017 Tue 00:03 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37056550**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3208 State of Registration: NY

Num of Occupants: 4 Driver's Age: 28 Sex: M Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031054 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Medburry Rd

12/22/2017 Fri 19:59 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37056552**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: NONE

Manner of Collision: RIGHT ANGLE Weather: CLOUDY

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 2380 State of Registration: NY

Num of Occupants: 2 Driver's Age: 22 Sex: M Citation Issued: N

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: VIEW OBSTRUCTED/LIMITED, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2773 State of Registration: NY

Num of Occupants: 1 Driver's Age: 50 Sex: F Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE LANE CHANGE, PASSING TOO CLOSELY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH State Highway 8

12/29/2017 Fri 15:43 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2017-37066270**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE Traffic Control: STOP SIGN

Manner of Collision: REAR END Weather: CLOUDY

Road Surface Condition: WET | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3361 State of Registration: NY

Num of Occupants: 1 Driver's Age: 25 Sex: M Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: FOLLOWING TOO CLOSELY, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 3120 State of Registration: NY

Num of Occupants: 1 Driver's Age: 49 Sex: F Citation Issued: N

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: STOPPED IN TRAFFIC

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
591 Meters South of Parker Rd

1/6/2018 Sat 20:52 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2018-37080738**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLL. W/EARTH CUT/DITCH ELE./ROCK Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT/ GRADE Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4975 State of Registration: NY

Num of Occupants: 2 Driver's Age: 17 Sex: F Citation Issued: N

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031100 Street: STATE HIGHWAY 8
21 Meters South of Old State Highway 8 N

1/13/2018 Sat 20:46 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2018-37087743**

Accident Class: PROPERTY DAMAGE Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLL. W/EARTH CUT/DITCH ELE./ROCK Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLEAR

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: DE

Num of Occupants: 1 Driver's Age: 27 Sex: M Citation Issued: Y

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031007 Street: STATE HIGHWAY 8
63 Meters North of Waterview Farm Ln

1/13/2018 Sat 22:44 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37092363**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3711 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 20 | Sex: M | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
321 Meters West of Phillip Odell Rd

1/19/2018 Fri 18:06 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37099566**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3280 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 18 | Sex: M | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031106 Street: STATE HIGHWAY 8
17 Meters South of County Road 33

1/18/2018 Thu 08:30 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2018-37103765**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NORWICH SP | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE

Manner of Collision: REAR END | Weather: CLEAR

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 TRUCK Registered Weight: State of Registration: AR

Num of Occupants: 1 | Driver's Age: 54 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: STOPPED IN TRAFFIC

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4508 State of Registration: NY

Num of Occupants: 1 | Driver's Age: 56 | Sex: F | Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, FOLLOWING TOO CLOSELY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031031 Street: STATE HIGHWAY 8
126 Meters South of Old State Highway 8 S

1/6/2018 Sat 13:03 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37113234**

Accident Class: PROPERTY DAMAGE | Police Agency: NEW BERLIN TOWM POLICE DEPT | Num of Veh: 1
Type Of Accident: COLLISION WITH OTHER FIXED OBJECT | Traffic Control: OTHER
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: SNOW/ICE | Road Char.: CURVE AND HILLCREST | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 OTHER Registered Weight: State of Registration: TX

Num of Occupants: 1 | Driver's Age: 23 | Sex: M | Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, DRIVER INEXPERIENCE

County: Chenango Muni: Bainbridge(T) Ref. Marker: 8 92031002 Street: STATE HIGHWAY 8
57 Meters South of Unnamed Street

1/29/2018 Mon 06:22 AM | Persons Killed: 0 | Persons Injured: 2 | Extent of Injuries: CC | **Case: 2018-37120302**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 4
Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NONE
Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DUSK
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :4 CAR/VAN/PICKUP Registered Weight: 5816 State of Registration: NY
Num of Occupants: 1 Driver's Age: 51 Sex: M Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 10000 State of Registration: NY
Num of Occupants: 1 Driver's Age: 25 Sex: M Citation Issued: Y
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: FOLLOWING TOO CLOSELY, UNSAFE SPEED

Veh :3 CAR/VAN/PICKUP Registered Weight: 3921 State of Registration: NY
Num of Occupants: 2 Driver's Age: 22 Sex: F Citation Issued: N
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: MAKING LEFT TURN
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :2 CAR/VAN/PICKUP Registered Weight: 2535 State of Registration: NY
Num of Occupants: 1 Driver's Age: 22 Sex: M Citation Issued: N
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
1377 Meters West of Mount Upton St

1/22/2018 Mon 04:25 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37127540**
Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLL. W/EARTH CUT/DITCH | ELE./ROCK | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4500 State of Registration: NY

Num of Occupants: 1 Driver's Age: 51 Sex: F Citation Issued: N

Direction of Travel: EAST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

2/2/2018 Fri 12:17 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2018-37134390**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL Traffic Control: NONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: SLUSH Road Char.: CURVE AND GRADE Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4038 State of Registration: NY

Num of Occupants: 1 Driver's Age: 35 Sex: F Citation Issued: N

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
1037 Meters South of Whites Hill Rd

2/9/2018 Fri 09:26 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2018-37143325**

Accident Class: NON-REPORTABLE Police Agency: CHENANGO CO SO Num of Veh: 1

Type Of Accident: COLLISION WITH SNOW EMBANKMENT Traffic Control: NONE

Manner of Collision: OTHER Weather: CLOUDY

Road Surface Condition: SNOW/ICE Road Char.: CURVE AND GRADE Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 23 Sex: M Citation Issued: N

Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
1067 Meters West of Keach Rd

2/22/2018 Thu 10:56 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37156303**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: CURVE AND GRADE | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2724 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 55 | Sex: F | Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
574 Meters South of Whites Hill Rd

2/22/2018 Thu 11:53 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37162828**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT AT HILLCREST | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2611 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 45 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031016 Street: STATE HWY 8
1003 Meters South of Unnamed Street

2/4/2018 Sun 10:57 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37167166**

Accident Class: NON-REPORTABLE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH FENCE | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: CURVE AND GRADE | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 17 | Sex: F | Citation Issued: N
Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: UNSAFE SPEED, PAVEMENT SLIPPERY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031047 Street: STATE HIGHWAY 8
328 Meters North of Hitching Post Ln

12/23/2016 Fri 18:50 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2016-37177906**
Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH ANIMAL | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3712 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 53 | Sex: M | Citation Issued: N
Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

3/13/2018 Tue 00:14 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37185440**
Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH FENCE | Traffic Control: NONE
Manner of Collision: OTHER | Weather: SNOW
Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: FL
Num of Occupants: 1 | Driver's Age: 23 | Sex: M | Citation Issued: Y
Direction of Travel: SOUTH-EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: TIRE FAILURE/INADEQUATE, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
AT INTERSECTION WITH Brownell Rd

3/13/2018 Tue 06:17 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2018-37185445**

Accident Class: PROPERTY DAMAGE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH SNOW EMBANKMENT Traffic Control: NONE

Manner of Collision: OTHER Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT/ GRADE Light Condition: DAWN

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4363 State of Registration: NY

Num of Occupants: 1 Driver's Age: 41 Sex: M Citation Issued: Y

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: TIRE FAILURE/INADEQUATE, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: Street: SHUMWAY RD
AT INTERSECTION WITH Driveway

3/9/2018 Fri 19:23 PM Persons Killed: 0 Persons Injured: 1 Extent of Injuries: C **Case: 2018-37208497**

Accident Class: PROPERTY DAMAGE AND INJURY Police Agency: NORWICH SP Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH Traffic Control: NONE

Manner of Collision: OTHER Weather: SNOW

Road Surface Condition: SNOW/ICE Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3810 State of Registration: NY

Num of Occupants: 1 Driver's Age: 44 Sex: F Citation Issued: Y

Direction of Travel: WEST Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031051 Street: STATE HIGHWAY 8

3/26/2018 Mon 14:50 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2018-37221122**

Accident Class: NON-REPORTABLE Police Agency: NYSP SIDNEY Num of Veh: 1

Type Of Accident: COLLISION WITH FENCE
Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER
Weather: CLEAR
Road Surface Condition: DRY
Road Char.: CURVE AND LEVEL
Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE
Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: PA
Num of Occupants: 1 Driver's Age: 48 Sex: M Citation Issued: Y
Direction of Travel: SOUTH
Public Property Damage: OTHER
School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: FELL ASLEEP, FAILURE TO KEEP RIGHT

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

4/7/2018
Sat 06:40 AM
Persons Killed: 0
Persons Injured: 0
Extent of Injuries:
Case: 2018-37223960
Accident Class: PROPERTY DAMAGE
Police Agency: NYSP SIDNEY
Num of Veh: 1
Type Of Accident: COLLISION WITH GUIDE RAIL
Traffic Control: NONE
Manner of Collision: OTHER
Weather: CLOUDY
Road Surface Condition: SNOW/ICE
Road Char.: CURVE AND LEVEL
Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE
Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3296 State of Registration: NY
Num of Occupants: 1 Driver's Age: 34 Sex: M Citation Issued: Y
Direction of Travel: WEST
Public Property Damage: OTHER
School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: PAVEMENT SLIPPERY, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031084 Street: STATE HIGHWAY 8
260 Meters North of Mill St

4/4/2018
Wed 15:29 PM
Persons Killed: 0
Persons Injured: 1
Extent of Injuries: A
Case: 2018-37229541
Accident Class: PROPERTY DAMAGE AND INJURY
Police Agency: NORWICH SP
Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE
Traffic Control: NO PASSING ZONE
Manner of Collision: REAR END
Weather: CLOUDY
Road Surface Condition: DRY
Road Char.: STRAIGHT AND LEVEL
Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE
Action of Ped/Bicycle: NOT APPLICABLE

Veh :2 BUS Registered Weight: State of Registration: NY
Num of Occupants: 4 Driver's Age: 64 Sex: M Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 6350 State of Registration: NY

Num of Occupants: 1 Driver's Age: 64 Sex: F Citation Issued: Y

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FELL ASLEEP, FOLLOWING TOO CLOSELY

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
958 Meters North of Joslyn Rd

4/6/2018 Fri 10:30 AM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2018-37229573**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLLISION WITH TREE | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 24 Sex: M Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, UNSAFE LANE CHANGE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH County Road 36

4/6/2018 Fri 11:00 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37231527**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLLISION WITH SIGN POST | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: SNOW

Road Surface Condition: SNOW/ICE | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NJ

Num of Occupants: 2 Driver's Age: 54 Sex: M Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING RIGHT TURN

Apparent Factors: TURNING IMPROPER, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031022 Street: STATE HIGHWAY 8
AT INTERSECTION WITH Unnamed Street

5/5/2018 Sat 04:27 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37269402**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH CUT/DITCH | ELE./ROCK | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2813 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 30 | Sex: F | Citation Issued: Y

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO KEEP RIGHT, FATIGUED/DROWSY

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031054 Street: STATE HIGHWAY 8
17 Meters South of Batterson Rd

5/17/2018 Thu 07:08 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37299763**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH CUT/DITCH | ELE./ROCK | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3748 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 19 | Sex: M | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FELL ASLEEP, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street:

5/29/2018 Tue 15:12 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37319307**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1
Type Of Accident: COLLISION WITH OTHER FIXED OBJECT | Traffic Control: STOP SIGN
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: | State of Registration: IL
Num of Occupants: 2 | Driver's Age: 40 | Sex: M | Citation Issued: N
Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: OBSTRUCTION/DEBRIS, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 37
1313 Meters West of Mount Upton St

6/21/2018 Thu 13:30 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37343363**
Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1
Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE
Manner of Collision: OTHER | Weather: CLEAR
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3205 | State of Registration: NY
Num of Occupants: 1 | Driver's Age: 58 | Sex: F | Citation Issued: N
Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
AT INTERSECTION WITH Ives Settlement Rd

6/22/2018 Fri 12:41 PM | Persons Killed: 0 | Persons Injured: 2 | Extent of Injuries: BC | **Case: 2018-37366454**
Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NORWICH SP | Num of Veh: 2
Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: NO PASSING ZONE
Manner of Collision: RIGHT ANGLE | Weather: CLOUDY
Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3572 State of Registration: NY

Num of Occupants: 1 Driver's Age: 80 Sex: F Citation Issued: Y

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: MAKING LEFT TURN

Apparent Factors: FAILURE TO YIELD RIGHT OF WAY, DRIVER INATTENTION

Veh :2 CAR/VAN/PICKUP Registered Weight: 3616 State of Registration: NY

Num of Occupants: 1 Driver's Age: 72 Sex: F Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35

7/22/2018 Sun 07:47 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37403938**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH GUIDE RAIL | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3807 State of Registration: NY

Num of Occupants: 2 Driver's Age: 19 Sex: F Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: DRIVER INATTENTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
409 Meters North of Joslyn Rd

7/11/2018 Wed 22:30 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37418677**

Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2976 State of Registration: NY

Num of Occupants: 1 Driver's Age: 44 Sex: M Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031021 Street: STATE HIGHWAY 8
119 Meters South of Unnamed Street

8/7/2018 Tue 12:25 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37437253**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 2

Type Of Accident: COLLISION WITH MOTOR VEHICLE | Traffic Control: MAINTENANCE WORK AREA

Manner of Collision: REAR END | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: CURVE AND LEVEL | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 TRUCK Registered Weight: State of Registration: NJ

Num of Occupants: 2 Driver's Age: 23 Sex: M Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: UNSAFE SPEED, DRIVER INATTENTION

Veh :2 CAR/VAN/PICKUP Registered Weight: 2786 State of Registration: NY

Num of Occupants: 1 Driver's Age: 38 Sex: F Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: SLOWED OR STOPPING

Apparent Factors: NOT APPLICABLE, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031038 Street: STATE HIGHWAY 8
546 Meters South of Rockdale Rd

8/29/2018 Wed 17:07 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: C | **Case: 2018-37471494**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLEAR

Road Surface Condition: DRY | Road Char.: STRAIGHT AT HILLCREST | Light Condition: DAYLIGHT

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3482 State of Registration: NY

Num of Occupants: 1 Driver's Age: 42 Sex: M Citation Issued: Y

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: DRUGS (ILLEGAL), FAILURE TO KEEP RIGHT

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 35
120 Meters North of Allen Rd

9/13/2018 Thu 21:49 PM | Persons Killed: 0 | Persons Injured: 1 | Extent of Injuries: B | **Case: 2018-37482413**

Accident Class: PROPERTY DAMAGE AND INJURY | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3901 State of Registration: NY

Num of Occupants: 2 Driver's Age: 60 Sex: F Citation Issued: N

Direction of Travel: EAST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031019 Street: STATE HIGHWAY 8
588 Meters South of Unnamed Street

9/21/2018 Fri 21:18 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37502292**

Accident Class: NON-REPORTABLE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: WET | Road Char.: STRAIGHT AND LEVEL | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: State of Registration: NY

Num of Occupants: 1 Driver's Age: 62 Sex: M Citation Issued: N

Direction of Travel: NORTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 37
78 Meters East of Brownell Rd

9/22/2018 Sat 04:25 AM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37504490**

Accident Class: PROPERTY DAMAGE | Police Agency: CHENANGO CO SO | Num of Veh: 1

Type Of Accident: COLL. W/EARTH ELE./ROCK CUT/DITCH | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: CURVE AND GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 2509 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 24 | Sex: M | Citation Issued: Y

Direction of Travel: WEST | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: FAILURE TO KEEP RIGHT, UNSAFE SPEED

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031069 Street: STATE HIGHWAY 8
798 Meters North of Hazy Ridge Ln

9/28/2018 Fri 20:04 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37509219**

Accident Class: PROPERTY DAMAGE | Police Agency: NYSP SIDNEY | Num of Veh: 1

Type Of Accident: COLLISION WITH ANIMAL | Traffic Control: NONE

Manner of Collision: OTHER | Weather: CLOUDY

Road Surface Condition: DRY | Road Char.: STRAIGHT/ GRADE | Light Condition: DARK-ROAD UNLIGHTED

Loc. of Ped/Bicycle: NOT APPLICABLE | Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP | Registered Weight: 3555 | State of Registration: NY

Num of Occupants: 1 | Driver's Age: 24 | Sex: F | Citation Issued: N

Direction of Travel: SOUTH | Public Property Damage: OTHER | School Bus Involved: OTHER

Pre-Accd Action: GOING STRAIGHT AHEAD

Apparent Factors: ANIMAL'S ACTION, NOT APPLICABLE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: COUNTY ROAD 36
549 Meters South of N Pond Rd

10/20/2018 Sat 17:03 PM | Persons Killed: 0 | Persons Injured: 0 | Extent of Injuries: | **Case: 2018-37538443**

Accident Class: PROPERTY DAMAGE | Police Agency: NORWICH SP | Num of Veh: 1

Type Of Accident: COLLISION WITH DEER | Traffic Control: NO PASSING ZONE

Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: WET Road Char.: STRAIGHT/ GRADE Light Condition: DAYLIGHT
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 3250 State of Registration: NY
Num of Occupants: 1 Driver's Age: 57 Sex: M Citation Issued: N
Direction of Travel: SOUTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, ANIMAL'S ACTION

County: Chenango Muni: Guilford(T) Ref. Marker: 8 92031071 Street: STATE HIGHWAY 8
602 Meters South of Easyliving Trailer Park

10/14/2018 Sun 23:21 PM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2018-37553526**
Accident Class: PROPERTY DAMAGE Police Agency: CHENANGO CO SO Num of Veh: 1
Type Of Accident: COLLISION WITH GUIDE RAIL Traffic Control: NONE
Manner of Collision: OTHER Weather: CLOUDY
Road Surface Condition: DRY Road Char.: STRAIGHT AND LEVEL Light Condition: DARK-ROAD UNLIGHTED
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 2613 State of Registration: NY
Num of Occupants: 2 Driver's Age: 24 Sex: F Citation Issued: N
Direction of Travel: NORTH Public Property Damage: OTHER School Bus Involved: OTHER
Pre-Accd Action: GOING STRAIGHT AHEAD
Apparent Factors: NOT APPLICABLE, TIRE FAILURE/INADEQUATE

County: Chenango Muni: Guilford(T) Ref. Marker: Street: [Route] 36
AT INTERSECTION WITH [Route] 35

10/18/2018 Thu 09:00 AM Persons Killed: 0 Persons Injured: 0 Extent of Injuries: **Case: 2018-37560176**
Accident Class: PROPERTY DAMAGE Police Agency: Num of Veh: 1
Type Of Accident: COLLISION WITH OTHER Traffic Control: UNKNOWN
Manner of Collision: OTHER Weather: UNKNOWN
Road Surface Condition: UNKNOWN Road Char.: UNKNOWN Light Condition: UNKNOWN
Loc. of Ped/Bicycle: NOT APPLICABLE Action of Ped/Bicycle: NOT APPLICABLE

Veh :1 CAR/VAN/PICKUP Registered Weight: 4524 State of Registration: NY
Num of Occupants: 1 Driver's Age: 64 Sex: M Citation Issued: N
Direction of Travel: UNKNOWN Public Property Damage: OTHER School Bus Involved: OTHER

Pre-Accd Action: BACKING

Apparent Factors: NOT ENTERED, NOT ENTERED